

Environmental Programs
P.O. Box 1663, MS M991
Los Alamos, New Mexico 87545
(505) 606-2337/FAX (505) 665-1812





National Nuclear Security Administration
Los Alamos Site Office, MS A316
Environmental Restoration Program
Los Alamos, New Mexico 87544
(505) 667-4255/FAX (505) 606-2132

Date: November 30, 2008 Refer To: EP2008-0612

James P. Bearzi, Bureau Chief Hazardous Waste Bureau New Mexico Environment Department 2905 Rodeo Park Drive East, Building 1 Santa Fe, NM 87505-6303

Subject: Submittal of Proof of Inspection of Erosion Controls in Drainages to the

90s Line Pond

Dear Mr. Bearzi:

Enclosed please find two hard copies with electronic files of this letter and associated photographs that document Los Alamos National Laboratory's (LANL's) annual inspection of the erosion controls deployed in the drainages to the 90s Line Pond. Documentation of annual inspections was required as part of the New Mexico Environment Department's (NMED's) "Notice of Approval with Direction Investigation Report for Consolidated Units 16-007(a)-99 and 16-008(a)-99 at Technical Area 16, Revision 1," dated February 11, 2008, and a subsequent NMED letter, "Approval of Erosion Controls Installed in Drainages to the 90s Line Pond, Consolidated Unit 16-008(a)-99," dated July 7, 2008.

The best management practices (BMPs) in the drainages associated with Consolidated Unit 16-008(a)-99 (the 90s Line) were inspected on October 31, 2008. The inspection team observed (1) no evidence of recent stormwater runoff; (2) no evidence of excessive recent erosion in the drainages; (3) no evidence of non-stormwater discharges; (4) the existing BMPs (juniper bales) are adequate for controlling sediment and erosion at the site; and (5) no maintenance is required. Four photographs documenting these inspections are included as Attachment 1.

If you have questions, please call John McCann at (505) 665-1091 (jmccann@lanl.gov) or Woody Woodworth at (505) 665-5820 (lwoodworth@doeal.gov).

Sincerely,

Michael J. Graham, Associate Director

Environmental Programs

Los Alamos National Laboratory

Sincerely,

David R. Gregory, Project Director

Environmental Operations Los Alamos Site Office James Bearzi EP2008-0612

MG/DG/DM/JM/DH:sm

Enclosure: Photographs documenting inspections (LA-UR-08-7492)

2

Cy: (w/enc.)

Don Hickmott, EP-CAP, MS M992 RPF, MS M707 (with two CDs) Public Reading Room, MS M992

Cy: (Letter and CD only)

Laurie King, EPA Region 6, Dallas, TX Steve Yanicak, NMED-OB, White Rock, NM Woody Woodworth, DOE-LASO, MS A316 Kristine Smeltz, WES-DO, MS M992 EP-CAP File, MS M992

Cy: (w/o enc.)

Tom Skibitski, NMED-OB, Santa Fe, NM Alison Bennett, DOE-LASO (date-stamped letter emailed) Michael J. Graham, ADEP, MS M991 Alison M. Dorries, WES-DO, MS M992 Dave McInroy, EP-CAP, MS M992 IRM-RMMSO, MS A150 (date-stamped letter emailed)




Photo 1 Annual BMP inspection of Consolidated Unit 16-008(a)-99. View to the west, looking at BMPs including juniper bales and vegetation.



Photo 2 Annual BMP inspection of Consolidated Unit 16-0089a)-99. View to the south, looking at BMPs including juniper bales and vegetation.



Photo 3 Annual BMP inspection of Consolidated Unit 16-008(a)-99. View to the southwest, looking at BMPs including juniper bales and vegetation.



Photo 4 Annual BMP inspection of Consolidated Unit 16-008(a)-99. View to the south, looking at BMPs including juniper bales and vegetation.