U.S. DEPARTMENT OF ENERGY

ESHID-603573

National Nuclear Security Administration
Los Alamos Field Office
3747 West Jemez Road, A316
Los Alamos, New Mexico 87544
(505) 667-5105/Fax (505) 667-5948

Environmental Management
Los Alamos Field Office
P.O. Box 1663, M984
Los Alamos, New Mexico 87544
(505) 257-7950/Fax (505) 665-5903

Date: FEB 2 6 2020
Symbol: EPC-DO-20-050
LA-UR: 20-21356
Locates Action No.: Not applicable

Mr. Kevin Pierard, Bureau Chief
Hazardous Waste Bureau
New Mexico Environment Department
2905 Rodeo Park Drive East, Building 1
Santa Fe, NM 87505-6313

Subject: **2019 Hazardous Waste Biennial Report for Los Alamos National Laboratory EPA ID# NM 0890010515**

Dear Mr. Pierard:

The National Nuclear Security Administration (NNSA), Environmental Management Los Alamos Field Office (EM-LA), Triad National Security, LLC (Triad), and Newport News Nuclear BWXT-Los Alamos, LLC (N3B), (collectively, the Permittees), submit the 2019 Hazardous Waste Biennial Report (HWBR) in accordance with Permit Section 2.12.5 of the Los Alamos National Laboratory (LANL) Hazardous Waste Facility Permit (Permit) to the New Mexico Environment Department Hazardous Waste Bureau (NMED-HWB).

Attached to this letter are Enclosures 1, HWBR - January 1, 2019, through December 31, 2019 for both Triad and N3B, to satisfy the reporting requirements as outlined in Section 2.12.5 of the Permit. Enclosure 2 includes Certifications signed by each of the responsible Permittees.

The Laboratory generates, stores, and treats hazardous and mixed waste on-site; however, all hazardous and mixed waste is disposed of off-site. The enclosed report documents the management (i.e., generation, treatment, or disposal) of RCRA hazardous and mixed waste containers at LANL during CY2019. This information has been compiled into the appropriate forms, and uploaded to the 2019 RCRA*Info* Web Portal. This year's report contains 454 waste Generation and Management (GM) forms. In CY2019, LANL generated a little more than 1414235 kilograms (kg) of RCRA hazardous waste with 1184756 kg of RCRA hazardous waste shipped off-site as a result of increased remediation activities to include contaminated soil. Shipments of transuranic (TRU) and mixed transuranic (MTRU) waste to the Waste

U.S. DEPARTMENT OF ENERGY

National Nuclear Security Administration
Los Alamos Field Office
3747 West Jemez Road, A316
Los Alamos, New Mexico 87544
(505) 667-5105/Fax (505) 667-5948

Environmental Management
Los Alamos Field Office
P.O. Box 1663, M984
Los Alamos, New Mexico 87544
(505) 257-7950/Fax (505) 665-5903

Date: FEB 26 2020
Symbol: EPC-DO-20-050
LA-UR: 20-21356
Locates Action No.: Not applicable

Mr. Kevin Pierard, Bureau Chief
Hazardous Waste Bureau
New Mexico Environment Department
2905 Rodeo Park Drive East, Building 1
Santa Fe, NM 87505-6313

Subject: **2019 Hazardous Waste Biennial Report for Los Alamos National Laboratory EPA ID# NM 0890010515**

Dear Mr. Pierard:

The National Nuclear Security Administration (NNSA), Environmental Management Los Alamos Field Office (EM-LA), Triad National Security, LLC (Triad), and Newport News Nuclear BWXT-Los Alamos, LLC (N3B), (collectively, the Permittees), submit the 2019 Hazardous Waste Biennial Report (HWBR) in accordance with Permit Section 2.12.5 of the Los Alamos National Laboratory (LANL) Hazardous Waste Facility Permit (Permit) to the New Mexico Environment Department Hazardous Waste Bureau (NMED-HWB).

Attached to this letter are Enclosures 1, HWBR - January 1, 2019, through December 31, 2019 for both Triad and N3B, to satisfy the reporting requirements as outlined in Section 2.12.5 of the Permit. Enclosure 2 includes Certifications signed by each of the responsible Permittees.

The Laboratory generates, stores, and treats hazardous and mixed waste on-site; however, all hazardous and mixed waste is disposed of off-site. The enclosed report documents the management (i.e., generation, treatment, or disposal) of RCRA hazardous and mixed waste containers at LANL during CY2019. This information has been compiled into the appropriate forms, and uploaded to the 2019 RCRA*Info* Web Portal. This year's report contains 454 waste Generation and Management (GM) forms. In CY2019, LANL generated a little more than 1414235 kilograms (kg) of RCRA hazardous waste with 1184756 kg of RCRA hazardous waste shipped off-site as a result of increased remediation activities to include contaminated soil. Shipments of transuranic (TRU) and mixed transuranic (MTRU) waste to the Waste

NNSA National Nuclear Security Administration

Isolation Pilot Plant (WIPP) presently continue to be shipped from LANL, following the February 2014 event, which temporarily closed the facility.

The Permittees would like to identify the following to the NMED-HWB:

- The United States Environmental Protection Agency (EPA) instructions for the 2019 HWBR RCRA Subtitle C Reporting Instructions and Forms (PDF), page 51, paragraph 7, identify hazardous wastewaters received by the Radioactive Liquid Waste Treatment Facility (RLWTF) are exempt from reporting. However, hazardous and mixed wastes generated by the RLWTF are sent to Technical Area (TA)-63, and then are disposed at an offsite facility. Those wastes are included in this report.

- In addition to EPA ID #NM890010515, LANL also owns and operates a second hazardous waste generating facility (Fenton Hill), EPA ID #NMD986676807. This facility did not generate any hazardous waste in calendar year 2019, and is not required to submit a HWBR for this facility.

- The HWBR GM forms include a field (1.F) to identify whether or not a specific waste stream has been reviewed for waste minimization opportunities. This field has an affirmative entry (i.e., A or B). LANL began or implemented waste minimization efforts at the waste stream profile level during CY2013. Legacy wastes generated before 2013, will be reported with an "X" (no minimization efforts) even if LANL had implemented waste minimization efforts during the year a given legacy waste was initially generated. Because of this, field 1.F on the enclosed GM forms significantly under-reports LANL's actual waste minimization efforts. Therefore, the reviewers are referred to the report entitled *"2019 Los Alamos National Laboratory Hazardous Waste Minimization Report" (LA-UR-19-31434)*, which was submitted to the NMED-HWB in November 2019. That report presents the complete details of LANL's facility-wide Waste Minimization program. Together, the 2019 HWBR and the 2017 Waste Minimization Report fulfill the requirements of 40 CFR Parts 262.41(6) and 262.41(7).

As recommended by EPA and the NMED-HWB, LANL used the RCRA*Info* web portal to upload an electronic version of the 2019 HWBR data for EPA ID # NM 0890010515.

If you have any questions regarding the contents of this report with Triad's Enclosure, please contact Ellena Martinez, Triad, at (505) 665-2751, martinezel@lanl.gov, Patrick Padilla, Triad, at (505) 667-3932, plpadilla@lanl.gov, or Karen Armijo at (505) 665-7314, karen.armijo@nnsa.doe.gov.

If you have any questions regarding the contents of this report with N3B's Enclosure, please contact Emily Day, N3B at (505) 695-4243, emily.day@em-la.doe.gov, Ellen Gammon, N3B, at (505) 309-1338, ellen.gammon@em-la.doe.gov, or Arturo Duran at (505) 257-7907.

Sincerely,

Karen E. Armijo
Permitting and Compliance Program Manager
National Nuclear Security Administration
Los Alamos Field Office
U.S. Department of Energy

Sincerely,

For Arturo Q. Duran
Permitting and Compliance Manager
Environmental Management
Los Alamos Field Office
U.S. Department of Energy

Enclosure(s): 1) Enclosure 1 – Triad and N3B 2019 Hazardous Waste Biennial Report (January 1, 2019, through December 31, 2019)

2) Enclosure 2 – Triad and N3B Certification

cc w/enclosures:

Copy: Laurie King, USEPA/Region 6, Dallas, TX, king.laurie@epa.gov
Kevin Pierard, NMED-HWB, Santa Fe, NM, kevin.pierard@state.nm.us
Peter Maggiore, NA-LA, peter.maggiore@nnsa.doe.gov
Jody M. Pugh, NA-LA, jody.pugh@nnsa.doe.gov
Karen E. Armijo, NA-LA, karen.armijo@nnsa.doe.gov
Adrienne L. Nash, NA-LA, adrienne.nash@nnsa.doe.gov
David Nickless, EM-LA, david.nickless@em.doe.gov
Arturo Duran, EM-LA, arturo.duran@em.doe.gov
Joseph Legare, N3B, joseph.legare@em-la.doe.gov
Elizabeth Lowes, N3B, elizabeth.lowes@em-la.doe.gov
Emily Day, N3B, emily.day@em-la.doe.gov
Gerald O'Leary, N3B, gerald.o'leary@em-la.doe.gov
Ellen Gammon, N3B, ellen.gammon@em-la.doe.gov
Pamela Maestas, N3B, pamela.maestas@em-la.doe.gov
Michael Hazen, ESHQSS, mhazen@lanl.gov
Enrique Torres, EWP, etorres@lanl.gov
Jennifer E. Payne, EPC-DO, jpayne@lanl.gov
Peter H. Carson, EPC-WMP, pcarson@lanl.gov
Ellena Martinez, EPC-WMP, martinezel@lanl.gov
Patrick Padilla, EPC-WMP, plpadilla@lanl.gov
adesh-records@lanl.gov
locatesteam@lanl.gov
epccorrespondence@lanl.gov
rcra-prr@lanl.gov
locatesteam@lanl.gov

Enclosure 1

Triad and N3B

2019 Biennial Hazardous Waste Report

(January 1, 2019, through December 31, 2019)

EPC-DO: 20-050

LA-UR-20-21356

Date: FEB 2 6 2020

Cycle	Site Name	Site ID
2019	LOS ALAMOS NATIONAL LABORATORY	NM0890010515

GM 1 Waste Characteristics			
A. Description of hazardous waste			
GENERATOR REFERENCE 09-22-06-01. INSPECTING, PACKAGING, REJECTING AND REMEDIATING TRANSURANIC WASTE FOR WIPP AND FOR...			
B. EPA Hazardous Waste Code(s)			
D004, D005, D006, D007, D008, D009, D010, D011, D018, D019, D021, D022, D035, D038, D039, D040, F001, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W519
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 182.9792
Comments			
1.E SOLIDIFIED AND REPACKAGED LABORATORY AND PRODUCTION DEBRIS			

GM 2 Waste Characteristics			
A. Description of hazardous waste			
GENERIC WPF FOR TRU WASTE PROCESSED UNDER THE TRANSURANIC WASTE CERTIFICATION PROGRAM (TWCP)			
B. EPA Hazardous Waste Code(s)			
D005, D006, D007, D008, D009, D010, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 22.6796
Comments			
1.D WASTE REPACKAGING OPERATIONS			

GM 3 Waste Characteristics			
A. Description of hazardous waste GENERIC WPF FOR TRU WASTE PROCESSED UNDER THE TRANSURANIC WASTE CERTIFICATION PROGRAM (TWCP)			
B. EPA Hazardous Waste Code(s) D006, D007, D008			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 165.9241
Comments			
1.D WASTE REPACKAGING OPERATIONS			

GM 4 Waste Characteristics			
A. Description of hazardous waste GENERIC WPF FOR TRU WASTE PROCESSED UNDER THE TRANSURANIC WASTE CERTIFICATION PROGRAM (TWCP)			
B. EPA Hazardous Waste Code(s) D007, D008, D009			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 4.7174
Comments			
1.D WASTE REPACKAGING OPERATIONS			

GM 5 Waste Characteristics			
A. Description of hazardous waste GENERIC WPF FOR TRU WASTE PROCESSED UNDER THE TRANSURANIC WASTE CERTIFICATION PROGRAM (TWCP)			
B. EPA Hazardous Waste Code(s) D008			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 83.461
Comments			
1.D WASTE REPACKAGING OPERATIONS			

GM 6 Waste Characteristics			
A. Description of hazardous waste (LEGACY WCCP) TRU LIQUID AND PARTICULATE WASTES IMMOBILIZED IN GYPSUM-BASED CEMENT.			
B. EPA Hazardous Waste Code(s) D006, D007, D008			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W319
F. Waste Minimization Code X	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 310.7108
Comments			
1.D STABILIZATION PROCESS; 1.E GYPSUM BASED CEMENT			

GM 7 Waste Characteristics			
A. Description of hazardous waste LEGACY TRU WASTE			
B. EPA Hazardous Waste Code(s) D007, D008			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 478.0601
Comments			
1.D WASTE REPACKAGING OPERATIONS			

GM 8 Waste Characteristics			
A. Description of hazardous waste LEGACY TRU WASTE			
B. EPA Hazardous Waste Code(s) D008			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 221.427
Comments			
1.D WASTE REPACKAGING OPERATIONS			

GM 9 Waste Characteristics			
A. Description of hazardous waste SPENT DRYBOX CATALYST			
B. EPA Hazardous Waste Code(s) D018, D028			
C. State Hazardous Waste Code(s)			
D. Source Code G08	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W310
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 38.9182	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 38.9182
Comments			

GM 10 Waste Characteristics			
A. Description of hazardous waste GEL PERMEATION WASTE SOLVENTS WITH TRACE HIGH EXPLOSIVES			
B. EPA Hazardous Waste Code(s) D001, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 27.2155
Comments			
1.D GEL PERMEATION CHROMATOGRAPHY AND HIGH PERFORMANCE LIQUID CHROMATOGRAPHY WASTE			

GM 11 Waste Characteristics			
A. Description of hazardous waste CONTAMINATED LEAD			
B. EPA Hazardous Waste Code(s) D008, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W307
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 175.9939	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 175.9939
Comments			

GM 12 Waste Characteristics			
A. Description of hazardous waste SULFURIC ACID SOLUTION			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G01	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.1793	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.1793
Comments			

GM 13 Waste Characteristics			
A. Description of hazardous waste CARBON SUPPORT TREATMENT FOR CATALYST.			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.7153	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.7153
Comments			

GM 14 Waste Characteristics			
A. Description of hazardous waste SPIN COATING PEROVSKITE SOLAR CELL			
B. EPA Hazardous Waste Code(s) D008, F002			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.6804	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.6804
Comments			
1.D SPIN COATING PEROVSKITE MATERIALS, ORGANIC SOLVENTS ONTO GLASS AND DEPOSITING METAL ELECTRODES ON TOP			

GM 15 Waste Characteristics

A. Description of hazardous waste

GT100PPM HIGH EXPLOSIVES IN METHANOL, ACETONITRILE AND WATER. NOT EXPLOSIVE IN THIS FORM.

B. EPA Hazardous Waste Code(s)

D001, F003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W203

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
50.3941	KILOGRAMS	1.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	95.7534

Comments

GM 16 Waste Characteristics

A. Description of hazardous waste

39-89 CERIUM METAL, ACETONE AND PPES

B. EPA Hazardous Waste Code(s)

D001, D003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
0.3629	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	0.3629

Comments

GM 17 Waste Characteristics			
A. Description of hazardous waste PBX 9501 MINOR COMPONENTS ANALYSIS BY LCMS			
B. EPA Hazardous Waste Code(s) D001, D028, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.79 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.1751
Comments			

GM 18 Waste Characteristics			
A. Description of hazardous waste GENERAL LAB TRASH CONTAINING BARIUM,CHROMIUM, SILVER, & CADMIUM COMPOUNDS.			
B. EPA Hazardous Waste Code(s) D005, D006, D007, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 7.2575	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 7.2575
Comments			

GM 19 Waste Characteristics			
A. Description of hazardous waste ACIDS, TOXIC METALS, OXIDIZER WASTE FROM NANOPARTICLES: SYNTHESIS, ARRAYS, COMPOSITE MATERIALS & SURFACE MODIFICATIONS			
B. EPA Hazardous Waste Code(s) D001, D002, D004, D006, D007, D008, D010, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 7.5296	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 7.5297
Comments			
1.D SYNTHESIS OF NANOPARTICLES			

GM 20 Waste Characteristics			
A. Description of hazardous waste SOLVENTS/ METALS/ SULFIDES, ETC. WASTE FROM NANOPARTICLES: SYNTHESIS, ARRAYS, COMPOSITE MATERIALS & SURFACE MODIFICATION			
B. EPA Hazardous Waste Code(s) D001, D003, D004, D006, D007, D008, D010, D011, D022, D029, F002, F003, F004, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 33.9287	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 33.9287
Comments			
1.D SYNTHESIS OF NANOPARTICLES			

GM 21 Waste Characteristics			
A. Description of hazardous waste LAB TRASH: SOLVENTS/ METALS/ REACTIVES FROM NANOPARTICLES: SYNTHESIS, ARRAYS, COMPOSITE MATERIALS & SURFACE MODIFICATION			
B. EPA Hazardous Waste Code(s) D003, D004, D006, D007, D008, D010, D011, D022, D029, F002, F004, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 45.9036	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 45.9035
Comments			
1.D SYNTHESIS OF NANOPARTICLES			

GM 22 Waste Characteristics			
A. Description of hazardous waste GENERAL PEPTIDE CLEAVAGE AND ETHER PRECIPTIATION IN SYNTHETIC/BIOCHEMISTRY RESEARCH OPERATIONS.			
B. EPA Hazardous Waste Code(s) D001, D002, D022, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W219
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.3587	*UOM* KILOGRAMS	*Density* 1.1 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.3587
Comments			
1.E TRIFLUOROACETIC ACID AND ETHYL ETHER ORGANIC WASTE			

GM 23 Waste Characteristics

A. Description of hazardous waste

ALLOY DEVELOPMENT FOR CRYSTAL GROWTH AND PHYSICAL PROPERTIES RESEARCH OPERATIONS.

B. EPA Hazardous Waste Code(s)

D004, D005, D006, D007, D008, D009, D010, D011, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
6.6224	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	6.6224

Comments

GM 24 Waste Characteristics

A. Description of hazardous waste

WASTE ORGANIC SOLVENTS FROM SAMPLE CLEANING AND DEGREASING

B. EPA Hazardous Waste Code(s)

D001, F003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W203

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
5.5338	KILOGRAMS	0.9 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	5.5338

Comments

GM 25 Waste Characteristics			
A. Description of hazardous waste WATER WITH ABRASIVE GRIT FROM HAZARDOUS METAL POLISHING			
B. EPA Hazardous Waste Code(s) D008, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 54.8847	*UOM* KILOGRAMS	*Density* 1.05 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 54.8847
Comments			
1.D GRINDING AND POLISHING METALLOGRAPHIC SAMPLES			

GM 26 Waste Characteristics			
A. Description of hazardous waste DNA AND OR RNA EXTRACTION			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.8579	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.8579
Comments			

GM 27 Waste Characteristics			
A. Description of hazardous waste SPENT SOLVENT (USED FOR CLEANING EQUIPMENT DURING PAINT OPERATIONS)			
B. EPA Hazardous Waste Code(s) D001, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G06	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 154.7657	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 105.2334
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 154.7657
Comments			

GM 28 Waste Characteristics			
A. Description of hazardous waste LAB. TRASH FROM SAMPLE PREP & EQUIPMENT MAINTENANCE THAT IS CONTAMINATED WITH SOLVENTS, DEGREASERS, EPOXIES, FOAMS			
B. EPA Hazardous Waste Code(s) D011, D035, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 11.9295	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 11.9295
Comments			

GM 29 Waste Characteristics

A. Description of hazardous waste

ACETONE FOR CLEANING MASS SPEC

B. EPA Hazardous Waste Code(s)

D001, F003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W203

F. Waste Minimization Code	*G. Radioactive Mixed*
A	Yes

H. Quantity	*UOM*	*Density*
2.0412	KILOGRAMS	1.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	FLD980711071	H061	2.0412

Comments

GM 30 Waste Characteristics

A. Description of hazardous waste

WASTE HALOGENATED AND NON-HALOGENATED SOLVENTS AND BY-PRODUCTS RESULTING FROM THE SYNTHESIS OF ORGANOMETALLIC AND ORG...

B. EPA Hazardous Waste Code(s)

D001, D019, D028, D033, F002, F003, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G19		UNITED STATES	W204

F. Waste Minimization Code	*G. Radioactive Mixed*
A	Yes

H. Quantity	*UOM*	*Density*
17.4633	KILOGRAMS	0.95 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	FLD980711071	H061	17.4633

Comments

1.D SYNTHESIS OF ORGANOMETALLIC, INORGANIC AND ORGANIC COMPOUNDS

GM 31 Waste Characteristics

A. Description of hazardous waste

WASTE FROM VARIOUS ANALYTICAL PROCEDURES

B. EPA Hazardous Waste Code(s)

D002, D004, D006, D007, D008, D009, D010, D011

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W103

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
222.351	KILOGRAMS	1.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	222.351

Comments

GM 32 Waste Characteristics

A. Description of hazardous waste

ORGANIC SOLVENTS USED FOR CLEANING METAL AND CERAMIC SPECIMENS FROM CORROSION STUDY EXPERIMENTS.

B. EPA Hazardous Waste Code(s)

D001, D007, F003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W203

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
3.0844	KILOGRAMS	0.85 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	3.0844

Comments

GM 33 Waste Characteristics			
A. Description of hazardous waste PHENOL:CHLOROFORM:ISOAMYL ALCOHOL SOLID WASTE FROM NUCLEIC ACID EXTRACTION FROM SOIL			
B. EPA Hazardous Waste Code(s) D022			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 8.1647	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 8.1647
Comments			

GM 34 Waste Characteristics			
A. Description of hazardous waste PHENOL/CHLOROFORM/ISOAMYL ALCOHOL LIQUID WASTE FROM DNA PURIFICATION.			
B. EPA Hazardous Waste Code(s) D001, D022			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W219
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.7216	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.7216
Comments			
1.E PHENOL AND CHLOROFORM			

GM 35 Waste Characteristics			
A. Description of hazardous waste OIL TITRATION BY-PRODUCT WASTE			
B. EPA Hazardous Waste Code(s) D001, D005, D006, D009, D010, D022, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G07	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 32.8401	*UOM* KILOGRAMS	*Density* 1.48 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 32.8401
Comments			

GM 36 Waste Characteristics			
A. Description of hazardous waste RINSE PRODUCT FROM SOUND VELOCITY AND DENSITY MEASUREMENTS OF CRUDE OIL SAMPLES			
B. EPA Hazardous Waste Code(s) D001, D009, D010, D018, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G13	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.9484	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.9484
Comments			

GM 37 Waste Characteristics			
A. Description of hazardous waste CLEANING OPERATION OF GAS-GUNS AT TA-40 BUILDING 9			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 45.1324
Comments			
1.D CLEAN-UP OPERATION OF GAS-GUNS			

GM 38 Waste Characteristics			
A. Description of hazardous waste ARATHANE, RESIN, HARDNER AND THINNER ARE MIXED FOR CONFORMAL COATING OF SPACE FLIGHT HARDWARE.			
B. EPA Hazardous Waste Code(s) D035			
C. State Hazardous Waste Code(s)			
D. Source Code G06	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 6.8039	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 6.8039
Comments			

GM 39 Waste Characteristics			
A. Description of hazardous waste MIN04 WASTE CONTAINERS (SALT WASTE)			
B. EPA Hazardous Waste Code(s) D004, D005, D006, D007, D008, D009, D010, D011, D018, D019, D021, D022, D035, D038, D039, D040, F001, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G07	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W316
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 63.5937
Comments			

GM 40 Waste Characteristics			
A. Description of hazardous waste ETHANOL SOLUTION			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 49.1694	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 49.1694
Comments			
1.D ETHYL ALCOHOL (ETHANOL) RINSE BATH			

GM 41 Waste Characteristics			
A. Description of hazardous waste GENERAL LAB TRASH FROM SAMPLE PREP AND EQUIPMENT MAINTENANCE THAT IS CONTAMINATED WITH SOLVENTS, DEGREASERS, EPOXIES, ...			
B. EPA Hazardous Waste Code(s) D008, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 17.5722	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 17.5722
Comments			

GM 42 Waste Characteristics			
A. Description of hazardous waste HE MACHINING OPERATIONS AT TA-16-260			
B. EPA Hazardous Waste Code(s) D003, D030			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W405
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 285.62	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Process System 1	*Management Method Code* H129	*Quantity* 285.62	
Off-site Shipment of Hazardous Waste			
Comments			
1.D HE MACHINING OPERATIONS			

GM 43 Waste Characteristics			
A. Description of hazardous waste ALCOHOLS, DESTAIN SOLUTION, COOMASSIE BLUE USED IN STAINING GELS.			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W219
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 12.4738	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 12.4738
Comments			
1.E METHANOL AND ALCOHOLS FOR STAINING PROTEIN GELS			

GM 44 Waste Characteristics			
A. Description of hazardous waste ETHANOL PRECIPITATION OF NUCLEIC ACIDS.			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.7216	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 2.7216
Comments			

GM 45 Waste Characteristics			
A. Description of hazardous waste PRECIPITATION OF PETN EXPLOSIVE AT TA-09-46.			
B. EPA Hazardous Waste Code(s) D001, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 537.9606
Comments			

GM 46 Waste Characteristics			
A. Description of hazardous waste CIN01 WASTE CONTAINERS			
B. EPA Hazardous Waste Code(s) D004, D005, D006, D007, D008, D009, D010, D011, D018, D019, D021, D022, D035, D038, D039, D040, F001, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W319
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 10784.5451
Comments			
1.D LIQUID WASTE NEUTRALIZATION AND SOLIDIFICATION; 1.E CEMENTED TRANSURANIC (MTRU) WASTE			

GM 47 Waste Characteristics

A. Description of hazardous waste

SOLID WASTE GENERATED IN THE SYNTHESIS, PURIFICATION, AND SAMPLE PREPARATION OF INORGANIC/ORGANOMETALLIC COMPOUNDS

B. EPA Hazardous Waste Code(s)

D006, D010, D011, F002, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G19		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
18.688	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	18.688

Comments

1.D SOLID WASTE GENERATED IN THE SYNTHETIC CHEMISTRY, PURIFICATION, AND PREPARATION OF ANALYTICAL SAMPLES

GM 48 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D001

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
236.1461	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H061	80.0137
Site 2	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	206.6173
Site 3	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	ILD098642424	H040	0.6804

Comments

GM 49 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D002			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 103.6967	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 3.6287
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 100.0679
Comments			

GM 50 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D002, D003			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 7.3936	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 7.3936
Comments			

GM 51 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D002, U006			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.6329	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.6329
Comments			

GM 52 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D002, U008, U123			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.4948	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.4948
Comments			

GM 53 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D002, U110			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 10.2058	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 10.2058
Comments			

GM 54 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D002, U122			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.2268	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.2268
Comments			

GM 55 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D003			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 53.6146	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 53.6146
Comments			

GM 56 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D003, P014			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.2268	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.2268
Comments			

GM 57 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D003, U077			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.4948	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.4948
Comments			

GM 58 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D003, U125			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.2268	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.2268
Comments			

GM 59 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D005			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.9958	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.9958
Comments			

GM 60 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D005, D008			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.4019	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.4019
Comments			

GM 61 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D001, D007

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
11.5212	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	11.5212

Comments

GM 62 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D001, D009

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
0.9072	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	0.9072

Comments

GM 63 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D001, D011

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
10.5233	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	10.5233

Comments

GM 64 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D001, D011, D035

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
3.4019	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	3.4019

Comments

GM 65 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D022			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.4019	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 3.4019
Comments			

GM 66 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D035			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 30.9577	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 62.0968
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 12.8593
Comments			

GM 67 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D035, U002, U154			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.9685	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 14.9685
Comments			

GM 68 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D035, U019, U056, U220			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.8967	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.8967
Comments			

GM 69 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D038			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 12.9274	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 12.9274
Comments			

GM 70 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U001, U002, U003, U031, U108			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.9685	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 14.9685
Comments			

GM 71 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D001, U001, U031, U056, U213

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
5.6699	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	5.6699

Comments

GM 72 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D001, U002, U154

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
15.3768	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H061	11.9748
Site 2	COD980591184	H141	3.4019

Comments

GM 73 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U003, U108, U154, U159, U220			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.9685	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 14.9685
Comments			

GM 74 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U025			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.2268	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.2268
Comments			

GM 75 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U031			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.1751	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 3.1751
Comments			

GM 76 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U031, U112, U196			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.8967	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.8967
Comments			

GM 77 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U053			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.2268	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.2268
Comments			

GM 78 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U056, U239			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 8.6183	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 8.6183
Comments			

GM 79 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U077			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.2617	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 5.2617
Comments			

GM 80 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U083			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.6308	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.6308
Comments			

GM 81 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U108			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 21.0013
Comments			

GM 82 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U108, U117, U213			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 6.5771	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 6.5771
Comments			

GM 83 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U108, U239			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 12.7006	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 12.7006
Comments			

GM 84 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U112, U154			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.8165	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.8165
Comments			

GM 85 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U154			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 21.7724	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 14.9685
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 6.8039
Comments			

GM 86 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U154, U220, U239			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.9685	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 14.9685
Comments			

GM 87 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U154, U239			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 4.7627	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 4.7627
Comments			

GM 88 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U159			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.4948	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.4948
Comments			

GM 89 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U160			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.6804	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.6804
Comments			

GM 90 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, U161			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.3608
Comments			

GM 91 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D001, U162

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
14.1521	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H061	14.1521

Comments

GM 92 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D001, U213

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
2.9937	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	2.9937

Comments

GM 93 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 472.3415	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 0.2268
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 497.3344
Comments			

GM 94 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D002, D003			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.2205	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 7.3936
Comments			

GM 95 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D002, D004, D005, D006, D007, D008, D010			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.1256	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.1256
Comments			

GM 96 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D002, D004, D005, D006, D007, D008, D010, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 47.7633	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 47.7633
Comments			

GM 97 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D002, D004, D005, D008, D010, D011

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
3.4019	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	3.4019

Comments

GM 98 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D002, D005, D006, D008

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
0.6804	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	0.6804

Comments

GM 99 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D002, D006, D007			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 8.1647	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 8.1647
Comments			

GM 100 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D002, D007			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.6699	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.6699
Comments			

GM 101 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D002, D009

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
6.3503	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	2.7216
Site 2	COD980591184	H061	3.6287

Comments

GM 102 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D002, D011

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
6.1235	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	6.1235

Comments

GM 103 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D002, U052			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.9009	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.9009
Comments			

GM 104 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) U103, D002			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.6783	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.6783
Comments			

GM 105 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D002, U122			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.5876	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.5876
Comments			

GM 106 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D002, U133			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.5897	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.5897
Comments			

GM 107 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D002, U134			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 7.1214	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 7.1214
Comments			

GM 108 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D003			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 29.2567	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 18.3705
Comments			

GM 109 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D003, D004, D010, U044, U170			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 4.3091	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 4.3091
Comments			

GM 110 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D003, D005, D007, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.3608	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.3608
Comments			

GM 111 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D003, D006			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.6699	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.6699
Comments			

GM 112 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D003, D010			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.5876	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.5876
Comments			

GM 113 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D003, P030			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.5876	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.5876
Comments			

GM 114 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D004			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.8198	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.8198
Comments			

GM 115 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D004, U188			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.1751	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.1751
Comments			

GM 116 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D005			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 10.6141	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 10.6141
Comments			

GM 117 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D005, D006			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.4948	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.4948
Comments			

GM 118 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D005, D007, D008			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.2205	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.2205
Comments			

GM 119 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D005, D007, D008, D010

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
2.6308	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	2.6308

Comments

GM 120 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

D007

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
3.4019	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	3.4019

Comments

GM 121 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D007, D008, D009			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.1319	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.1319
Comments			

GM 122 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D008			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 46.8107	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 46.8107
Comments			

GM 123 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D008, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 9.5254	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 9.5254
Comments			

GM 124 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D008, U144			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.769	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.769
Comments			

GM 125 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D009			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.2268	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.2268
Comments			

GM 126 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D010			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 8.1647	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 8.1647
Comments			

GM 127 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D011			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.839	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 14.839
Comments			

GM 128 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D022, U044			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.7195
Comments			

GM 129 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D022, U044, U211			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 10.4326	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 10.4326
Comments			

GM 130 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D024, U052			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.2268	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.2268
Comments			

GM 131 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

U012

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
1.134	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	1.134

Comments

GM 132 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

U044

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
7.9379	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H061	4.7627
Site 2	COD980591184	H141	3.1751

Comments

GM 133 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

U044, U068, U169, U225

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
5.4431	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	5.4431

Comments

GM 134 Waste Characteristics

A. Description of hazardous waste

UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE

B. EPA Hazardous Waste Code(s)

U052

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
1.5876	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	1.5876

Comments

GM 135 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) U067			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.4536	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.4536
Comments			

GM 136 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) U067, U070, U169			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.4019	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.4019
Comments			

GM 137 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) U105			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.6804	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.6804
Comments			

GM 138 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) U149			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.134	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.134
Comments			

GM 139 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) U151			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 4.5359	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 4.5359
Comments			

GM 140 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) U188			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.3662	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.3662
Comments			

GM 141 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) U219			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.5876	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.5876
Comments			

GM 142 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) U227, U228			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.6699	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.6699
Comments			

GM 143 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) U328			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.2226	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.2226
Comments			

GM 144 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D001, D003, P022, U077			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W004
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 4.3091	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 4.3091
Comments			

GM 145 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D003, D008, P030			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W004
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.134	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.134
Comments			

GM 146 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D003, D010, P030			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W004
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.134	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.134
Comments			

GM 147 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D003, D011, P030			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W004
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.5876	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.5876
Comments			

GM 148 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D003, D022, P030			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W004
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.9504	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.9504
Comments			

GM 149 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D003, P030			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W004
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 4.037	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.3566
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 0.6804
Comments			

GM 150 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) D004, P012			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W004
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.6804	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.6804
Comments			

GM 151 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) P015			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W004
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.4536	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.4536
Comments			

GM 152 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) P042, U007			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W004
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.1751	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.1751
Comments			

GM 153 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT ACUTE RCRA HAZARDOUS/DOT LAB PACK WASTE			
B. EPA Hazardous Waste Code(s) P120			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W004
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.5876	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.5876
Comments			

GM 154 Waste Characteristics			
A. Description of hazardous waste METAL CONTAINING HALOGENATED AND NON HALOGENATED ORGANIC WASTE.			
B. EPA Hazardous Waste Code(s) D001, D007, D011, D019, D022, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 184.0882	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 15.4221
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 168.6661
Comments			
1.D SYNTHESIS AND CLEANING			

GM 155 Waste Characteristics

A. Description of hazardous waste

SOLID WASTE GENERATED BY SYNTHESIS AND CLEANING PROCESS INVOLVING ORGANIC AND ORGANOMETALLIC PROCEDURES

B. EPA Hazardous Waste Code(s)

D007, D011, D022, F002, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G09		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
87.0897	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	77.1107

Comments

1.D SYNTHESIS AND CLEANING PROCESS

GM 156 Waste Characteristics

A. Description of hazardous waste

GENERAL LAB TRASH FROM SAMPLE PREP & EQUIPMENT MAINTENANCE THAT IS CONTAMINATED WITH SOLVENTS, DEGREASERS, EPOXIES

B. EPA Hazardous Waste Code(s)

D011, F002, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
3.7648	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	3.7648

Comments

GM 157 Waste Characteristics			
A. Description of hazardous waste ACID AND INORGANIC WASTE: FOR GRAPHENE WORK			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 13.0635	*UOM* KILOGRAMS	*Density* 1.08 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 13.0635
Comments			

GM 158 Waste Characteristics			
A. Description of hazardous waste ACID WASTES FROM LABORATORY GLASSWARE CLEANING.			
B. EPA Hazardous Waste Code(s) D002, D018, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 12.9274	*UOM* KILOGRAMS	*Density* 1.1 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 12.9274
Comments			

GM 159 Waste Characteristics			
A. Description of hazardous waste HYDROCHLORIC ACID AND WATER USED FOR PARTS CLEANING			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 22.226	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 22.226
Comments			
1.D PARTS CLEANING OPERATIONS			

GM 160 Waste Characteristics			
A. Description of hazardous waste DEBRIS WASTE CONTAINERS			
B. EPA Hazardous Waste Code(s) D004, D005, D006, D007, D008, D009, D010, D011, D018, D019, D021, D022, D035, D038, D039, D040, F001, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 1224.9196
Comments			
1.D WASTE REPACKAGING OPERATIONS			

GM 161 Waste Characteristics			
A. Description of hazardous waste DEBRIS WASTE CONTAINERS			
B. EPA Hazardous Waste Code(s) D004, D005, D006, D007, D008, D009, D010, D011, D018, D019, D021, D022, D035, D038, D039, D040, F001, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 831.4349
Comments			
1.D WASTE REPACKAGING OPERATIONS			

GM 162 Waste Characteristics			
A. Description of hazardous waste 40-41 C4H16BN AND SAMPLE PREP TRASH			
B. EPA Hazardous Waste Code(s) D003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 4.5359	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 4.5359
Comments			

GM 163 Waste Characteristics			
A. Description of hazardous waste SOLID WASTE FROM THIN FILM PREPARATIONS			
B. EPA Hazardous Waste Code(s) D008, D010			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 47.7179	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 57.9691
Comments			
1.D THIN FILM PREPARATION			

GM 164 Waste Characteristics			
A. Description of hazardous waste HAZARDOUS WASTE CYLINDERS-NOT DESTINED FOR GAS PLANT			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W801
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 7.0307	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 9.2986
Comments			

GM 165 Waste Characteristics			
A. Description of hazardous waste HAZARDOUS WASTE CYLINDERS-NOT DESTINED FOR GAS PLANT			
B. EPA Hazardous Waste Code(s) D001, D002			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W801
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H129	*D. Total Quantity Shipped* 2.7216
Comments			

GM 166 Waste Characteristics			
A. Description of hazardous waste HAZARDOUS WASTE CYLINDERS-NOT DESTINED FOR GAS PLANT			
B. EPA Hazardous Waste Code(s) D001, D003, U135			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W801
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.5876	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.5876
Comments			

GM 167 Waste Characteristics			
A. Description of hazardous waste HAZARDOUS WASTE CYLINDERS-NOT DESTINED FOR GAS PLANT			
B. EPA Hazardous Waste Code(s) D001, U115			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W801
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.3608
Comments			

GM 168 Waste Characteristics			
A. Description of hazardous waste HAZARDOUS WASTE CYLINDERS-NOT DESTINED FOR GAS PLANT			
B. EPA Hazardous Waste Code(s) D001, U135			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W801
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.8144
Comments			

GM 169 Waste Characteristics			
A. Description of hazardous waste HAZARDOUS WASTE CYLINDERS-NOT DESTINED FOR GAS PLANT			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W801
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H129	*D. Total Quantity Shipped* 1.3608
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.3608
Comments			

GM 170 Waste Characteristics			
A. Description of hazardous waste HAZARDOUS WASTE CYLINDERS-NOT DESTINED FOR GAS PLANT			
B. EPA Hazardous Waste Code(s) D002, D003			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W801
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.1751
Comments			

GM 171 Waste Characteristics

A. Description of hazardous waste

MLLW DEBRIS WASTE CONTAINERS FROM TRU OPERATIONS

B. EPA Hazardous Waste Code(s)

D004, D005, D006, D007, D008, D009, D010, D011, D018, D019, D021, D022, D026, D027, D028, D029, D030, D035, D036, D037, D038, D039, D040, D043, F001, F002, F004, F005, F006, F007, F009

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G19		UNITED STATES	W409

F. Waste Minimization Code	*G. Radioactive Mixed*
A	Yes

H. Quantity	*UOM*	*Density*
0.0	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	TXD988088464	H132	71.5769

Comments

1.D WASTE REPACKAGING OPERATIONS; 1.E PAPER, RAGS, PLASTIC, RUBBER, WOOD BASED HIGH-EFFICIENCY PARTICULATE AIR (HEPA) FILTERS, OTHER PLASTIC BASED AND CELLULOSE BASED ITEMS

GM 172 Waste Characteristics

A. Description of hazardous waste

ACID/ PHENOL CARBOHYDRATE ASSAY

B. EPA Hazardous Waste Code(s)

D002

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W103

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
4.037	KILOGRAMS	1.84 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	4.037

Comments

GM 173 Waste Characteristics			
A. Description of hazardous waste TA-46-31 LABORATORY TRASH DERIVED FROM THE SYNTHESIS AND PURIFICATION OF ORGANIC AND INORGANIC COMPLEXES.			
B. EPA Hazardous Waste Code(s) D007, D022, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 4.0823	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 4.0823
Comments			

GM 174 Waste Characteristics			
A. Description of hazardous waste ISOLATION OF PYOCYANIN BY CHLOROFORM EXTRACTION.			
B. EPA Hazardous Waste Code(s) D022			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W219
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 6.5317	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 6.5317
Comments			
1.E CHLOROFORM/HYDROCHLORIC ACID SOLUTION			

GM 175 Waste Characteristics			
A. Description of hazardous waste TETRAHYDROFURAN USED FOR GPC ANALYSES			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.89 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.6287
Comments			

GM 176 Waste Characteristics			
A. Description of hazardous waste TA-46-24 LABORATORY TRASH DERIVED FROM PURIFICATION OF ORGANIC AND INORGANIC COMPLEXES			
B. EPA Hazardous Waste Code(s) D007, D022, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 8.6183	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 8.6183
Comments			

GM 177 Waste Characteristics			
A. Description of hazardous waste 39-89 CERIUM METAL POWDER IN MINERAL OIL			
B. EPA Hazardous Waste Code(s) D001, D003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W219
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.3629	*UOM* KILOGRAMS	*Density* 0.88 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.3629
Comments			
1.E CERIUM POWDER IN MINERAL OIL			

GM 178 Waste Characteristics			
A. Description of hazardous waste CONATHANE EN-4 AND EN-7 CONTAMINATED WASTE MATERIAL FROM THE SOLDERING AND POTTING SUPPLY CONNECTOR PROCESS			
B. EPA Hazardous Waste Code(s) D003, U223			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.4473	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 6.7358
Comments			
1.D POTTING OF POWER SUPPLY CONNECTORS			

GM 179 Waste Characteristics			
A. Description of hazardous waste AQUEOUS (BASIC) WASTE: R&D SYNTHESIS OF POLYMERS SURFACTANT CHEMISTRY FOR FORMING NANOSTRUCTURES			
B. EPA Hazardous Waste Code(s) D001, D002, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W110
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.8967	*UOM* KILOGRAMS	*Density* 1.5 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.8967
Comments			

GM 180 Waste Characteristics			
A. Description of hazardous waste MERCURY CONTAMINATED MLLW LUJAN FLIGHT PATH REMOVAL			
B. EPA Hazardous Waste Code(s) D009			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 4.5359	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 4.5359
Comments			

GM 181 Waste Characteristics			
A. Description of hazardous waste MLLW GENERATED DURING LUJAN FLIGHT PATH REMOVAL			
B. EPA Hazardous Waste Code(s) D004, D005, D006, D007, D008, D010, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W319
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 39.4625	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 39.4625
Comments			
1.D ROUTINE MAINTENANCE AND HOUSEKEEPING; 1.E METALS AND SOLIDS CONTAINING RCRA METALS			

GM 182 Waste Characteristics			
A. Description of hazardous waste ELECTROPOLISH SOLUTION WITH PHOSPHORIC ACID IN WATER AND ORGANIC SOLVENT FOR ELECTROPOLISHING			
B. EPA Hazardous Waste Code(s) D001, D002, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.8165	*UOM* KILOGRAMS	*Density* 1.2 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.8165
Comments			

GM 183 Waste Characteristics			
A. Description of hazardous waste 40-8 SPENT GBX DEVELOPER (KODAK)			
B. EPA Hazardous Waste Code(s) D010			
C. State Hazardous Waste Code(s)			
D. Source Code G08	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 54.3404	*UOM* KILOGRAMS	*Density* 1.07 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 54.3404
Comments			

GM 184 Waste Characteristics			
A. Description of hazardous waste MISCELLANEOUS ELECTRONICS POTENTIAL INTERNAL RADIOACTIVE CONTAMINATION			
B. EPA Hazardous Waste Code(s) D006, D008, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 285.3096	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 285.3096
Comments			

GM 185 Waste Characteristics			
A. Description of hazardous waste AQUEOUS COPPER/MERCURY WASTE			
B. EPA Hazardous Waste Code(s) D002, D007, D009			
C. State Hazardous Waste Code(s)			
D. Source Code G02	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 46.0396	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 46.0396
Comments			

GM 186 Waste Characteristics			
A. Description of hazardous waste CONTAMINATED LAB TRASH - SOLIDS			
B. EPA Hazardous Waste Code(s) F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 36.0606	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 4.9895
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 33.8834
Comments			

GM 187 Waste Characteristics			
A. Description of hazardous waste CATALYST INKS			
B. EPA Hazardous Waste Code(s) D001, D010, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W209
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 20.0941	*UOM* KILOGRAMS	*Density* 2.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 20.0941
Comments			
1.E CATALYST INKS OF CARBON, NANOCARBON AND PRECIOUS METALS			

GM 188 Waste Characteristics			
A. Description of hazardous waste ELECTROCHEMICAL SOLUTIONS: PERCHLORIC/SULFURIC ACID			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.7418	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 14.7418
Comments			

GM 189 Waste Characteristics			
A. Description of hazardous waste CATALYST POWDER SAMPLES			
B. EPA Hazardous Waste Code(s) D010			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W409
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 4.3545	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 4.3545
Comments			
1.E CATALYST POWDER SAMPLES WILL CONTAIN CARBON OR CARBON NANOMATERIALS ALONG WITH ONE OR MORE OF THE TRANSITION METALS OR PRECIOUS METALS			

GM 190 Waste Characteristics			
A. Description of hazardous waste SYNTHESIS OF CARBON BASED NON-PRECIOUS METAL CATALYSTS			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 55.1115	*UOM* KILOGRAMS	*Density* 1.2 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 55.1115
Comments			

GM 191 Waste Characteristics			
A. Description of hazardous waste PGM FREE CATALYST WASTE (FOR FOREIGN NATIONAL: XI YIN)			
B. EPA Hazardous Waste Code(s) D002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.2882	*UOM* KILOGRAMS	*Density* 1.1 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 14.2882
Comments			

GM 192 Waste Characteristics			
A. Description of hazardous waste ALKALINE ELECTROLYTE (HOON CHUNG)			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W110
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 15.4675	*UOM* KILOGRAMS	*Density* 1.2 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 15.4675
Comments			

GM 193 Waste Characteristics			
A. Description of hazardous waste SOLVENTS USED FOR WASHING SLIDES			
B. EPA Hazardous Waste Code(s) D001, D022, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G01	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 27.6691	*UOM* KILOGRAMS	*Density* 1.4 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 27.6691
Comments			

GM 194 Waste Characteristics			
A. Description of hazardous waste TA55 GROUP C TRU DRUMS CONVERTED TO MLLW W/ BERYLLIUM, BASED ON FAR FIELD GAMMA SPECTROSCOPY			
B. EPA Hazardous Waste Code(s) D004, D005, D006, D007, D008, D009, D010, D011, D018, D019, D021, D022, D035, D038, D039, D040, F001, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* TXD988088464	*C. Management Method Code* H132	*D. Total Quantity Shipped* 54.4764
Comments			
1.D MTRU WASTE PACKAGING AND REPACKAGING OPERATIONS			

GM 195 Waste Characteristics			
A. Description of hazardous waste LAB TRASH CONTAMINATED WITH MERCURY FROM POROSIMETER OPERATION			
B. EPA Hazardous Waste Code(s) D009			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.134	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.134
Comments			
1.D PORE SIZE ANALYSIS			

GM 196 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENT WASTE GENERATED FROM EXTRACTIONS, REACTIONS, AND WASHING ORGANIC COMPOUNDS FROM GLASSWARE.			
B. EPA Hazardous Waste Code(s) D001, D022, D038, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 130.3171	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 58.332
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 71.9851
Comments			

GM 197 Waste Characteristics			
A. Description of hazardous waste CR(VI) IN WATER BY ION EXCHANGE CHROMATOGRAPHY			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W105
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 54.2043	*UOM* KILOGRAMS	*Density* 1.1 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 54.2043
Comments			

GM 198 Waste Characteristics			
A. Description of hazardous waste SPIN COATING PEROVSKITE SOLAR CELL			
B. EPA Hazardous Waste Code(s) D008, D011, D021, F002			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 11.7934	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 11.7934
Comments			
1.D SPIN COATING PEROVSKITE MATERIALS, ORGANIC SOLVENTS ONTO GLASS AND DEPOSITING METAL ELECTRODES ON TOP			

GM 199 Waste Characteristics			
A. Description of hazardous waste GENERATION OF PHOSPHORIC ACID WASTE			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 6.1689	*UOM* KILOGRAMS	*Density* 1.5 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 6.1689
Comments			

GM 200 Waste Characteristics			
A. Description of hazardous waste HEXANES AND ETHYLACETATE RECOVERED FROM SOLVENT STILL			
B. EPA Hazardous Waste Code(s) D001, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 70.08	*UOM* KILOGRAMS	*Density* 0.66 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 70.08
Comments			
1.D MAINTENANCE OF SOLVENT STILL			

GM 201 Waste Characteristics

A. Description of hazardous waste

TRIETHYLAMINE/N-DECANE, AND ALIQUAT336/ XYLENES AND TBP/ DODECANE WITH METAL SALTS

B. EPA Hazardous Waste Code(s)

D001, F003, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W203

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
0.0	KILOGRAMS	1.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	12.0656

Comments

GM 202 Waste Characteristics

A. Description of hazardous waste

WATER LAYERS FROM EXTRACTIONS

B. EPA Hazardous Waste Code(s)

F002

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W113

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
13.1542	KILOGRAMS	1.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H061	13.1542

Comments

GM 203 Waste Characteristics			
A. Description of hazardous waste ALIQUAT336/ XYLENES AND TBP/ DODECANE WITH METAL SALTS- RAD			
B. EPA Hazardous Waste Code(s) D001, D002, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 22.6796	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* FLD980711071	*C. Management Method Code* H061	*D. Total Quantity Shipped* 22.6796
Comments			

GM 204 Waste Characteristics			
A. Description of hazardous waste NITRIC ACID SOLUTION USED IN TARGET FABRICATION OPERATIONS			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G02	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 11.0223	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 11.0223
Comments			

GM 205 Waste Characteristics

A. Description of hazardous waste

AQUEOUS WASTE GENERATED FROM EXTRACTIONS, REACTIONS, AND WASHING ORGANIC COMPOUNDS FROM GLASSWARE.

B. EPA Hazardous Waste Code(s)

D022, F002, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W113

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
34.9266	KILOGRAMS	1.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	34.9266

Comments

GM 206 Waste Characteristics

A. Description of hazardous waste

REDOX FLOW BATTERY PROCESS WASTE

B. EPA Hazardous Waste Code(s)

D002

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W103

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
7.7564	KILOGRAMS	1.2 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	7.7564

Comments

GM 207 Waste Characteristics			
A. Description of hazardous waste HF SILICA ETCHANT			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 47.219	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 47.219
Comments			

GM 208 Waste Characteristics			
A. Description of hazardous waste AQUEOUS (ACID) WASTE: R&D SYNTHESIS OF SURFACTANT-TEMPLATED GOLD AND SILVER NANOSTRUCTURES			
B. EPA Hazardous Waste Code(s) D001, D002, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 20.956	*UOM* KILOGRAMS	*Density* 1.5 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 20.956
Comments			

GM 209 Waste Characteristics

A. Description of hazardous waste

AQUEOUS (BASIC) WASTE: R&D SYNTHESIS OF POLYMERS SURFACTANT CHEMISTRY FOR FORMING NANOSTRUCTURES

B. EPA Hazardous Waste Code(s)

D001, D002, D011

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W110

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
85.5475	KILOGRAMS	1.5 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	85.5475

Comments

GM 210 Waste Characteristics

A. Description of hazardous waste

ROUTINE MAINTENANCE AND HOUSEKEEPING

B. EPA Hazardous Waste Code(s)

D008

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G09		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	Yes

H. Quantity	*UOM*	*Density*
304.0	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	UTD982598898	H132	2856.3733

Comments

1.D ROUTINE MAINTENANCE AND HOUSEKEEPING

GM 211 Waste Characteristics

A. Description of hazardous waste

POLYMER MEMBRANE, FILM, AND FIBER PROCESSING AND CHARACTERIZATION

B. EPA Hazardous Waste Code(s)

D038, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G06		UNITED STATES	W219

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
60.7814	KILOGRAMS	1.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H061	60.7814

Comments

1.E POLYMER PROCESSING AND CHARACTERIZATION

GM 212 Waste Characteristics

A. Description of hazardous waste

DETERMINING BROMINE TITRATION PROCESS.

B. EPA Hazardous Waste Code(s)

D001, F003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W113

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
2.268	KILOGRAMS	1.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	2.268

Comments

GM 213 Waste Characteristics			
A. Description of hazardous waste THE WASTE STREAM CONSISTS OF NUMEROUS INSECTS THAT WERE TAKEN AS SAMPLES OF VARIOUS AQUIFERS			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.0412	*UOM* KILOGRAMS	*Density* 0.79 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.0412
Comments			

GM 214 Waste Characteristics			
A. Description of hazardous waste HPLC PURIFICATION IN SYNTHETIC/BIOCHEMISTRY RESEARCH OPERATIONS.			
B. EPA Hazardous Waste Code(s) D001, D002, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W219
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.1521	*UOM* KILOGRAMS	*Density* 1.1 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 14.1521
Comments			
1.E AQUEOUS ACETONITRILE WASTE			

GM 215 Waste Characteristics			
A. Description of hazardous waste TUNGSTEN AND ALUMINA EVAPORATION CONTAINERS			
B. EPA Hazardous Waste Code(s) D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.1361
Comments			

GM 216 Waste Characteristics			
A. Description of hazardous waste ALKALINE WASTE STREAM			
B. EPA Hazardous Waste Code(s) D010, D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W110
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 7.6204	*UOM* KILOGRAMS	*Density* 1.02 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 7.6204
Comments			

GM 217 Waste Characteristics			
A. Description of hazardous waste MSL INFILL ORGANIC SOLVENT WASTE STREAM			
B. EPA Hazardous Waste Code(s) D001, D008, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 12.9727	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 12.9727
Comments			

GM 218 Waste Characteristics			
A. Description of hazardous waste MSL INFILL ACID WASTE STREAM			
B. EPA Hazardous Waste Code(s) D001, D002, D008			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 11.0677	*UOM* KILOGRAMS	*Density* 1.2 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 11.0677
Comments			

GM 219 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENTS WASTE			
B. EPA Hazardous Waste Code(s) D001, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 48.988	*UOM* KILOGRAMS	*Density* 0.95 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 16.1025
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 32.8854
Comments			

GM 220 Waste Characteristics			
A. Description of hazardous waste CATALYST SYNTHESIS WASTE			
B. EPA Hazardous Waste Code(s) D001, D022, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 12.4738	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 12.4738
Comments			

GM 221 Waste Characteristics			
A. Description of hazardous waste MIXED AQUEOUS ALKALINE WASTE			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 18.8241	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 18.8241
Comments			

GM 222 Waste Characteristics			
A. Description of hazardous waste LABORATORY TRASH WITH TETRAMETHYLAMMONIUM BOROHYDRIDE			
B. EPA Hazardous Waste Code(s) D003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.8	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 33.5
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.8
Comments			

GM 223 Waste Characteristics

A. Description of hazardous waste

MIXED LOW LEVEL WASTE NI-CAD BATTERY

B. EPA Hazardous Waste Code(s)

D006

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G15		UNITED STATES	W309

F. Waste Minimization Code	*G. Radioactive Mixed*
A	Yes

H. Quantity	*UOM*	*Density*
0.0	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	FLD980711071	H110	1.134

Comments

GM 224 Waste Characteristics

A. Description of hazardous waste

METAL BOXES WITH HIGH EXPLOSIVE (HE) CONTAMINATION

B. EPA Hazardous Waste Code(s)

D003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G15		UNITED STATES	W307

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
3.63	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

	Management Method Code	*Quantity*
Process System 1	H129	3.63

Off-site Shipment of Hazardous Waste

Comments

GM 225 Waste Characteristics

A. Description of hazardous waste

LIQUID WASTE GENERATED IN THE SYNTHESIS, PURIFICATION, AND SAMPLE PREPARATION OF INORGANIC/ORGANOMETALLIC POLYMERS

B. EPA Hazardous Waste Code(s)

D001, D011, D022, D035, F002, F003, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W204

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
23.2239	KILOGRAMS	0.9 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	23.2239

Comments

GM 226 Waste Characteristics

A. Description of hazardous waste

PLD LAB 1819-104 HAZARDOUS SOLID WASTE

B. EPA Hazardous Waste Code(s)

D005, D007, D011

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
3.4473	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	3.4473

Comments

GM 227 Waste Characteristics			
A. Description of hazardous waste AQUEOUS WASTE GENERATED FROM EXTRACTIONS, REACTIONS, AND WASHING ORGANIC COMPOUNDS FROM GLASSWARE.			
B. EPA Hazardous Waste Code(s) D001, D022, F002, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 17.1458	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Comments			

GM 228 Waste Characteristics			
A. Description of hazardous waste OXYGEN CELLS NON-RAD			
B. EPA Hazardous Waste Code(s) D002, D008			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W319
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 6.1235	*UOM* KILOGRAMS	*Density* 1.51 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 6.1235
Comments			
1.E OXYGEN SENSORS, SEALED CYLINDERS			

GM 229 Waste Characteristics			
A. Description of hazardous waste 3D PRINTING LIQUID WASTE			
B. EPA Hazardous Waste Code(s) F003, D001, D011, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 10.4326	*UOM* KILOGRAMS	*Density* 0.92 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 10.4326
Comments			
1.D PRINTING, CLEANING, PROCESSING 3D PRINTED PARTS			

GM 230 Waste Characteristics			
A. Description of hazardous waste AQUEOUS WASTE FROM CERAMIC POWDER COPRECIPITATION			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 9.344	*UOM* KILOGRAMS	*Density* 1.1 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 9.344
Comments			

GM 231 Waste Characteristics			
A. Description of hazardous waste DIESEL FUEL			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W211
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 11.2945	*UOM* KILOGRAMS	*Density* 0.85 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 8.6183
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.6762
Comments			

GM 232 Waste Characteristics			
A. Description of hazardous waste LIQUID WASTE GENERATED IN THE SYNTHESIS, PURIFICATION, AND SAMPLE PREPARATION OF INORGANIC/ORGANOMETALLIC COMPOUNDS			
B. EPA Hazardous Waste Code(s) D001, D006, D010, D011, D022, D028, F002, F003, F004, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 129.4553	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 41.6398
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 87.8155
Comments			

GM 233 Waste Characteristics			
A. Description of hazardous waste PIRANHA ETCH SOLUTION WASTE			
B. EPA Hazardous Waste Code(s) D001, D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.8555	*UOM* KILOGRAMS	*Density* 1.5 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.8555
Comments			

GM 234 Waste Characteristics			
A. Description of hazardous waste TMAB (TETRAMETHYLAMMONIUM BOROHYDRIDE) DISSOLUTION WITH DMSO AND THF			
B. EPA Hazardous Waste Code(s) D001, D003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.6804	*UOM* KILOGRAMS	*Density* 1.1 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.6804
Comments			

GM 235 Waste Characteristics			
A. Description of hazardous waste NITRIC ACID SOLUTIONS			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.1256	*UOM* KILOGRAMS	*Density* 1.5 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.1256
Comments			

GM 236 Waste Characteristics			
A. Description of hazardous waste MISCELLANEOUS ELECTRONICS AND EQUIPMENT			
B. EPA Hazardous Waste Code(s) D006, D007, D008, D010, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 440.8918	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 440.8918
Comments			

GM 237 Waste Characteristics			
A. Description of hazardous waste ROUTINE MAINTENANCE AND HOUSEKEEPING-LEAD-CADMIUM DEBRIS			
B. EPA Hazardous Waste Code(s) D006, D008			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W320
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 683.1826	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 683.1826
Comments			

GM 238 Waste Characteristics			
A. Description of hazardous waste BASIC: TRIETHYLAMINE/N-DECANE ALIQUAT336/ XYLENES, AND TBP/ DODECANE WITH METAL SALTS			
B. EPA Hazardous Waste Code(s) D001, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 6.8039	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 6.8039
Comments			

GM 239 Waste Characteristics

A. Description of hazardous waste

SOLIDS: TRIETHYLAMINE/N-DECANE ALIQUAT336/ XYLENES, AND TBP/ DODECANE WITH METAL SALTS

B. EPA Hazardous Waste Code(s)

F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
3.4473	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	3.4473

Comments

GM 240 Waste Characteristics

A. Description of hazardous waste

SYNTHESIS, PURIFICATION, AND SAMPLE PREPARATION OF INORGANIC/ORGANOMETALLIC COMPOUNDS 1698-C143

B. EPA Hazardous Waste Code(s)

D001, D006, D010, D011, D018, D022, D028, D036, D038, F002, F003, F004, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W204

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
3.9916	KILOGRAMS	0.9 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	3.9916

Comments

GM 241 Waste Characteristics			
A. Description of hazardous waste WASTE FROM SYNTHESIS OF ORGANOMETALLIC, ORGANIC, AND INORGANIC COMPOUNDS.			
B. EPA Hazardous Waste Code(s) D001, D021, D022, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 98.3388	*UOM* KILOGRAMS	*Density* 1.5 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 73.3005
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 25.0383
Comments			

GM 242 Waste Characteristics			
A. Description of hazardous waste TA-46_ELECTROCHEMICAL ACTIVITIES AND AMALGAMATION OF TRANSITION METALS AND LANTHANIDES			
B. EPA Hazardous Waste Code(s) D009			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 6.8039	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 6.8039
Comments			

GM 243 Waste Characteristics			
A. Description of hazardous waste UNUSED/USPENT FLAMMABLE LIQUIDS FROM ROOM 63 FLAMMABLE CABINET			
B. EPA Hazardous Waste Code(s) D001, D035			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 19.9581	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* FLD980711071	*C. Management Method Code* H061	*D. Total Quantity Shipped* 19.9581
Comments			

GM 244 Waste Characteristics			
A. Description of hazardous waste ACTIVATION PROTECTION (AP) CANS			
B. EPA Hazardous Waste Code(s) D008, D009, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W219
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 4.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* FLD980711071	*C. Management Method Code* H110	*D. Total Quantity Shipped* 87.0897
Comments			
1.E EXPIRED LAB PRODUCT CONTAINING 1,2,4 TIRMTHYLBENZENE, MINERAL OIL AND SCINILLATION CHEMICALS			

GM 245 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENT FOR PCB EXTRACTION			
B. EPA Hazardous Waste Code(s) D001, F002, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.0614	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 14.0614
Comments			

GM 246 Waste Characteristics			
A. Description of hazardous waste SOLID WASTE FROM PCB COLUMN CLEANUP			
B. EPA Hazardous Waste Code(s) F002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W319
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 11.5	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 11.5
Comments			
1.E SILICA GEL AND SODIUM SULFATE SOLIDS FROM LAB EXPERIMENTS			

GM 247 Waste Characteristics			
A. Description of hazardous waste POLYMERS AND LAB TRASH HAZARDOUS WASTE			
B. EPA Hazardous Waste Code(s) D003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.2268	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.2268
Comments			

GM 248 Waste Characteristics			
A. Description of hazardous waste MECHANICAL SAMPLE PREPARATION WASTE WITH TOXICITY CHARACTERISTIC METALS AND KEROSENE			
B. EPA Hazardous Waste Code(s) D005, D006, D008, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G05	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 9.35	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 9.35
Comments			

GM 249 Waste Characteristics

A. Description of hazardous waste

MECHANICAL SAMPLE PREPARATION WASTE WITH BERYLLIUM, SILVER, AND KEROSENE

B. EPA Hazardous Waste Code(s)

D011

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G05		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
1.2	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	1.2

Comments

GM 250 Waste Characteristics

A. Description of hazardous waste

LIQUID WASTE GENERATED IN THE SYNTHESIS, PURIFICATION, AND SAMPLE PREPARATION OF INORGANIC/ORGANOMETALLIC POLYMERS 1420

B. EPA Hazardous Waste Code(s)

D001, D011, D022, D035, F002, F003, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W204

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
82.1909	KILOGRAMS	0.9 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	82.1909

Comments

GM 251 Waste Characteristics			
A. Description of hazardous waste METHANOL /PHOSPHORIC ACID / AMMONIUM SULFATE/ USED IN STAINING GELS.			
B. EPA Hazardous Waste Code(s) D001, D002, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.0614	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 14.0614
Comments			

GM 252 Waste Characteristics			
A. Description of hazardous waste MLLW SEALED RADIOACTIVE SOURCE(S) GENERATED THROUGHOUT LANL.			
B. EPA Hazardous Waste Code(s) D008			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W319
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* TXD988088464	*C. Management Method Code* H132	*D. Total Quantity Shipped* 4.3091
Comments			
1.E RADIOACTIVE SEALED SOURCES			

GM 253 Waste Characteristics			
A. Description of hazardous waste AQUEOUS WASTE FROM FABRICATING SENSITIZED SOLAR CELLS			
B. EPA Hazardous Waste Code(s) D003, D010, D022			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 7.0307	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 7.0307
Comments			

GM 254 Waste Characteristics			
A. Description of hazardous waste MACHINING AND MECHANICAL CHARACTERIZATION OF MOCK HIGH EXPLOSIVE (HE) MATERIAL.			
B. EPA Hazardous Waste Code(s) D001, D005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W319
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.4494	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.4494
Comments			
1.E LAB TRASH, BARIUM, AND MACHINE STOCK			

GM 255 Waste Characteristics			
A. Description of hazardous waste POLYMER SYNTHESIS			
B. EPA Hazardous Waste Code(s) D001, D018, D022, D028, D035, D038, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 42.1387	*UOM* KILOGRAMS	*Density* 1.1 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 42.1387
Comments			

GM 256 Waste Characteristics			
A. Description of hazardous waste BROKEN MERCURY THERMOMETER			
B. EPA Hazardous Waste Code(s) D009			
C. State Hazardous Waste Code(s)			
D. Source Code G32	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.2722	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.2722
Comments			

GM 257 Waste Characteristics			
A. Description of hazardous waste 3D PRINTING SOLID WASTE			
B. EPA Hazardous Waste Code(s) D001, D011, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 7.0307	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 7.0307
Comments			
1.D PRINTING, CLEANING, PROCESSING 3D PRINTED PARTS			

GM 258 Waste Characteristics			
A. Description of hazardous waste LAB TRASH WITH SOLVENTS AND METALS FROM SAMPLE PREP			
B. EPA Hazardous Waste Code(s) D007, D008, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.9958	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.9958
Comments			

GM 259 Waste Characteristics			
A. Description of hazardous waste R & D PROCESS FOR SYNTHESIS 0F COMPOUNDS			
B. EPA Hazardous Waste Code(s) D001, D007, D011, D018, D019, D021, D022, D028, D038, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 119.5216	*UOM* KILOGRAMS	*Density* 0.95 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 27.6691
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 91.8525
Comments			

GM 260 Waste Characteristics			
A. Description of hazardous waste SOLID TRASH FROM R & D COMPOUNDS SYNTHESIS PROCESS			
B. EPA Hazardous Waste Code(s) D007, D011, D018, D019, D022, D028, D038, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 76.2035	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 76.2035
Comments			

GM 261 Waste Characteristics

A. Description of hazardous waste

CLEANING AND ETCHING WITH AQUEOUS MIXTURE OF HYDROFLUORIC ACID 1420-1221

B. EPA Hazardous Waste Code(s)

D002

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G04		UNITED STATES	W103

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
1.4515	KILOGRAMS	1.15 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	1.4515

Comments

GM 262 Waste Characteristics

A. Description of hazardous waste

POTASSIUM AND ARSENIC WASTE IN MINERAL OIL FROM CRYSTAL GROWTH OPERATIONS

B. EPA Hazardous Waste Code(s)

D001, D003, D004

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W219

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
5.0802	KILOGRAMS	0.85 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	5.0802

Comments

1.E CRYSTAL GROWTH SAMPLES IN MINERAL OIL

GM 263 Waste Characteristics			
A. Description of hazardous waste ELECTROLESS GOLD			
B. EPA Hazardous Waste Code(s) D002, D003			
C. State Hazardous Waste Code(s)			
D. Source Code G03	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W107
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.9958	*UOM* KILOGRAMS	*Density* 1.06 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.9958
Comments			

GM 264 Waste Characteristics			
A. Description of hazardous waste LAB TRASH CONTAMINATED WITH SOLVENTS, ALUMINA AND SILICA			
B. EPA Hazardous Waste Code(s) F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.7871	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 14.7871
Comments			

GM 265 Waste Characteristics

A. Description of hazardous waste

LEFTOVER TURPENTINE

B. EPA Hazardous Waste Code(s)

D001

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G11		UNITED STATES	W001

F. Waste Minimization Code	*G. Radioactive Mixed*
A	Yes

H. Quantity	*UOM*	*Density*
0.0	KILOGRAMS	0.86 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	FLD980711071	H061	3.0

Comments

GM 266 Waste Characteristics

A. Description of hazardous waste

3D PRINTER HEPA VACUUM WATER WITH METAL POWDERS

B. EPA Hazardous Waste Code(s)

D001

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G05		UNITED STATES	W113

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
290.3899	KILOGRAMS	1.1 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	290.3898

Comments

GM 267 Waste Characteristics			
A. Description of hazardous waste SOLID WASTE, HAZARDOUS LAB TRASH FROM CRYSTAL GROWTH/SAMPLE PREPARATION OPERATIONS			
B. EPA Hazardous Waste Code(s) D003, D004, D005, D006, D007, D008, D010, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 4.6266	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 4.6266
Comments			

GM 268 Waste Characteristics			
A. Description of hazardous waste COPPER NITRATE/NITRIC ACID WASTE			
B. EPA Hazardous Waste Code(s) D001, D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.4019	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.4019
Comments			

GM 269 Waste Characteristics			
A. Description of hazardous waste SMALL PARTICLE TRANSFER POLYMER WASTE			
B. EPA Hazardous Waste Code(s) D040			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W403
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.6804	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.6804
Comments			

GM 270 Waste Characteristics			
A. Description of hazardous waste ZINC SULFIDE NP, ALKALINE AQUEOUS WASTE			
B. EPA Hazardous Waste Code(s) D002, D003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W110
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.0844	*UOM* KILOGRAMS	*Density* 1.02 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.0844
Comments			

GM 271 Waste Characteristics

A. Description of hazardous waste

ORGANIC SOLVENT WASTE GENERATED FROM EXTRACTIONS, REACTIONS, AND WASHING ORGANIC COMPOUNDS FROM GLASSWARE - #1

B. EPA Hazardous Waste Code(s)

D001, F003, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W203

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
3.8555	KILOGRAMS	0.9 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	3.8555

Comments

GM 272 Waste Characteristics

A. Description of hazardous waste

SOLID TRASH FROM R&D SYNTHESIS PROCESS

B. EPA Hazardous Waste Code(s)

D001, D004, D007, D008, D010, D011, D018, D019, D021, D022, D028, D035, D038, F002, F003, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
2.0412	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	2.0412

Comments

GM 273 Waste Characteristics			
A. Description of hazardous waste PRECIPITATION OF PETN EXPLOSIVE AT TA-09-46.			
B. EPA Hazardous Waste Code(s) D001, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1544.7543	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2062.3032
Comments			

GM 274 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENT WASTE GENERATED FROM EXTRACTIONS, REACTIONS, PURIFICATIONS AND WASHING ORGANICS FROM GLASSWARE-SS			
B. EPA Hazardous Waste Code(s) D001, D022, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 23.986	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 23.986
Comments			

GM 275 Waste Characteristics

A. Description of hazardous waste

BROKEN MERCURY THERMOMETER

B. EPA Hazardous Waste Code(s)

D009

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G32		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
1.5422	KILOGRAMS	13.56 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	1.5422

Comments

GM 276 Waste Characteristics

A. Description of hazardous waste

CLEAR EC RESIN PREPARATION

B. EPA Hazardous Waste Code(s)

D001, F003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G07		UNITED STATES	W203

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
15.0139	KILOGRAMS	1.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Comments

GM 277 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENT WASTE GENERATED FROM CHROMATOGRAPHY			
B. EPA Hazardous Waste Code(s) D001, F002, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.5338	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.5338
Comments			

GM 278 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENT WASTE GENERATED FROM CHROMATOGRAPHY - BIOTAGE REVERSE PHASE			
B. EPA Hazardous Waste Code(s) D001, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 33.5658	*UOM* KILOGRAMS	*Density* 0.95 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 5.1256
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 28.4402
Comments			

GM 279 Waste Characteristics			
A. Description of hazardous waste ALODINE MATERIALS			
B. EPA Hazardous Waste Code(s) D007			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.35	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.35
Comments			

GM 280 Waste Characteristics			
A. Description of hazardous waste 3D PRINTER FILTER MEDIA WITH METAL POWDERS			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G05	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W310
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1245.5647	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1245.5648
Comments			

GM 281 Waste Characteristics

A. Description of hazardous waste

KIMWIPES, CLEAN ROOM WIPES, AND FILTERMEDIA FROM PETN PRECIPITATION ACTIVITIES AT TA-9-46

B. EPA Hazardous Waste Code(s)

D003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G09		UNITED STATES	W405

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
4.54	POUNDS	0.0 sg

On-site Generation and Management of Hazardous Waste

Process System 1	*Management Method Code*	*Quantity*
	H129	4.54

Off-site Shipment of Hazardous Waste

Comments

1.D CLEANUP OF EQUIPMENT AND MACHINERY WITH HIGH EXPLOSIVE

GM 282 Waste Characteristics

A. Description of hazardous waste

GEL PERMEATION WASTE SOLVENTS WITH TRACE HIGH EXPLOSIVES

B. EPA Hazardous Waste Code(s)

D001, F003, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W203

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
75.6592	KILOGRAMS	0.9 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	75.6592

Comments

GM 283 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENT WASTE GENERATED FROM CHROMATOGRAPHY - BIOTAGE REVERSE PHASE-GREATER THEN 50% H2O			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 35.7159	*UOM* KILOGRAMS	*Density* 0.95 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 30.0278
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.688
Comments			

GM 284 Waste Characteristics			
A. Description of hazardous waste REMEDIATION OF MERCURY DETECTED ABOVE THE SOIL BACKGROUND VALUE (BV).			
B. EPA Hazardous Waste Code(s) D009			
C. State Hazardous Waste Code(s)			
D. Source Code G49	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W319
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 961.6159	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2045.7017
Comments			
1.E MERCURY CONTAMINATED SOIL			

GM 285 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENT WASTE			
B. EPA Hazardous Waste Code(s) D001, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 4.3545	*UOM* KILOGRAMS	*Density* 0.8 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 4.3545
Comments			

GM 286 Waste Characteristics			
A. Description of hazardous waste SOLVENTS USED FOR CLEANING METALLOGRAPHIC SAMPLES			
B. EPA Hazardous Waste Code(s) D001, D011, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 17.85	*UOM* KILOGRAMS	*Density* 0.85 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 17.85
Comments			

GM 287 Waste Characteristics			
A. Description of hazardous waste IGNITABLE METAL POWDERS AND OXIDES			
B. EPA Hazardous Waste Code(s) D001, D003, D007, D008, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 7.9	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 7.9
Comments			

GM 288 Waste Characteristics			
A. Description of hazardous waste SM34 B13 ORGANIC SOLVENT WASTE STREAM			
B. EPA Hazardous Waste Code(s) D001, D008, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 4.0823	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 4.0823
Comments			

GM 289 Waste Characteristics

A. Description of hazardous waste

ELECTROLESS NICKEL PLATING SOLIDS CONTAINING MERCURY

B. EPA Hazardous Waste Code(s)

D009

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G32		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
2.1	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	2.1

Comments

GM 290 Waste Characteristics

A. Description of hazardous waste

SOLID WASTE FROM SYNTHESIS AND PURIFICATION OF TRANSITION METAL AND MAIN GROUP COMPOUNDS

B. EPA Hazardous Waste Code(s)

D022, F002, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
100.3346	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	119.0227

Comments

GM 291 Waste Characteristics			
A. Description of hazardous waste STANDARDS WITH MERCURY			
B. EPA Hazardous Waste Code(s) D002, D004, D006, D007, D008, D009, D010, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W119
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.5443	*UOM* KILOGRAMS	*Density* 1.02 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* FLD980711071	*C. Management Method Code* H110	*D. Total Quantity Shipped* 0.5443
Comments			
1.E EXPIRED AQUEOUS LAB STANDARDS			

GM 292 Waste Characteristics			
A. Description of hazardous waste STANDARDS WITHOUT MERCURY			
B. EPA Hazardous Waste Code(s) D002, D004, D005, D006, D007, D008, D010, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W119
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 7.4843	*UOM* KILOGRAMS	*Density* 1.02 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* FLD980711071	*C. Management Method Code* H110	*D. Total Quantity Shipped* 7.4843
Comments			
1.E EXPIRED AQUEOUS LAB STANDARDS			

GM 293 Waste Characteristics			
A. Description of hazardous waste LABORATORY EQUIPMENT AND TRASH WITH TETRAMETHYLAMMONIUM BOROHYDRIDE			
B. EPA Hazardous Waste Code(s) D003, D008, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 368.317	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 368.317
Comments			

GM 294 Waste Characteristics			
A. Description of hazardous waste 3D PRINTER FILTER MEDIA WITH METAL POWDERS			
B. EPA Hazardous Waste Code(s) D001, D003			
C. State Hazardous Waste Code(s)			
D. Source Code G05	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W310
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 527.5	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 471.3668
Comments			

GM 295 Waste Characteristics			
A. Description of hazardous waste LUJAN FLIGHT PATH EXPERIMENTAL SAMPLES			
B. EPA Hazardous Waste Code(s) D006, D008			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 24.9476	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* TXD988088464	*C. Management Method Code* H132	*D. Total Quantity Shipped* 4.9895
Comments			

GM 296 Waste Characteristics			
A. Description of hazardous waste SPENT SODIUM HYDROXIDE ETCHANT AND WATER WITH PH LT 12.5			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G04	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W110
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3057.6664	*UOM* KILOGRAMS	*Density* 2.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3057.6664
Comments			

GM 297 Waste Characteristics			
A. Description of hazardous waste 3D PRINTING LIQUID WASTE G105-3			
B. EPA Hazardous Waste Code(s) D001, D011, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W219
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.8513	*UOM* KILOGRAMS	*Density* 0.9 sg	

On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 5.8513
Comments			
1.D PRINTING, CLEANING, PROCESSING 3D PRINTED PARTS			

GM 298 Waste Characteristics			
A. Description of hazardous waste 455 HYDRIDE WASTE			
B. EPA Hazardous Waste Code(s) D001, D003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 1.7237	*UOM* KILOGRAMS	*Density* 0.0 sg	

On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* FLD980711071	*C. Management Method Code* H110	*D. Total Quantity Shipped* 1.7237
Comments			

GM 299 Waste Characteristics			
A. Description of hazardous waste SOLVENT WASTE C218			
B. EPA Hazardous Waste Code(s) D001, D009, D010, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 24.0404	*UOM* KILOGRAMS	*Density* 0.8 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 24.0404
Comments			

GM 300 Waste Characteristics			
A. Description of hazardous waste TETRAMETHYLAMMONIUM BOROHYDRIDE DISSOLUTION			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W110
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 15.3314	*UOM* KILOGRAMS	*Density* 1.2 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 15.3314
Comments			

GM 301 Waste Characteristics			
A. Description of hazardous waste HYDROCHLORIC ACID AND WATER USED FOR PARTS CLEANING			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 60.2371	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 60.2371
Comments			
1.D CLEANING OF COPPER PARTS			

GM 302 Waste Characteristics			
A. Description of hazardous waste INHERITED LIQUID WASTE G105			
B. EPA Hazardous Waste Code(s) D001, D011, D018, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W219
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.5855	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 2.5855
Comments			
1.D CLEANING OF PRODUCTS FROM 3D PRINTING; 1.E FLAMMABLE LIQUIDS CONTAINING NON-RCRA LISTED SOLVENTS			

GM 303 Waste Characteristics			
A. Description of hazardous waste 3D PRINTING SOLID WASTE			
B. EPA Hazardous Waste Code(s) D001, D011, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 7.5296	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 7.5296
Comments			
1.D CLEANING OF PRODUCTS FROM 3D PRINTING			

GM 304 Waste Characteristics			
A. Description of hazardous waste COPPER TUBING WITH SILVER SOLDER FROM TA-50 BUILDING-1 PIPING SYSTEM.			
B. EPA Hazardous Waste Code(s) D011			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W307
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* TXD988088464	*C. Management Method Code* H132	*D. Total Quantity Shipped* 5.5792
Comments			
1.D ROUTINE MAINTENANCE AND HOUSEKEEPING			

GM 305 Waste Characteristics			
A. Description of hazardous waste NANOPARTICLES SYNTHESIS GLASSWARE BASE BATH CLEANING SOLUTION			
B. EPA Hazardous Waste Code(s) D001, D002, D006, D008, D010, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 7.7111	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 7.7111
Comments			

GM 306 Waste Characteristics			
A. Description of hazardous waste NANOPARTICLE SYNTHESIS, SURFACE MODIFICATION, FILM DEPOSITION, AND SAMPLE PREPARATION ORGANIC LIQUID WASTE			
B. EPA Hazardous Waste Code(s) D001, D004, D005, D006, D008, D009, D010, D011, D019, D021, D022, D028, D035, D038, D039, D040, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 211.3741	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 211.3741
Comments			

GM 307 Waste Characteristics			
A. Description of hazardous waste NANOPARTICLE SYNTHESIS, SURFACE MODIFICATION, FILM DEPOSITION, AND SAMPLE PREPARATION SOLID WASTE			
B. EPA Hazardous Waste Code(s) D001, D004, D005, D006, D008, D010, D011, D019, D021, D022, D028, D035, D038, D039, D040, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 71.6676	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 71.6676
Comments			

GM 308 Waste Characteristics			
A. Description of hazardous waste NANOPARTICLES SYNTHESIS ACIDIC AQUEOUS WASTE			
B. EPA Hazardous Waste Code(s) D001, D002, D006, D008, D009, D010, D011, D022, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 12.9274	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 12.9274
Comments			

GM 309 Waste Characteristics			
A. Description of hazardous waste BACL2 AQUEOUS SOLUTION			
B. EPA Hazardous Waste Code(s) D005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 11.113	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 11.113
Comments			

GM 310 Waste Characteristics			
A. Description of hazardous waste SOLVENTS FROM THE SYNTHESIS AND PURIFICATION OF PEPTOIDS			
B. EPA Hazardous Waste Code(s) D001, D022, D028, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.8 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 90.8999
Comments			

GM 311 Waste Characteristics			
A. Description of hazardous waste BERYLLIUM CONTAMINATED ELECTRONICS			
B. EPA Hazardous Waste Code(s) D008, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W320
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 562.001	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 562.001
Comments			

GM 312 Waste Characteristics			
A. Description of hazardous waste MULTILAYERED CHEMICAL SYNTHESIS WASTE: ORGANIC SOLVENTS AND PRECIPITATE			
B. EPA Hazardous Waste Code(s) D001, D005, D007, D008, D009, D010, D019, D022, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 26.0362	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 26.0362
Comments			

GM 313 Waste Characteristics			
A. Description of hazardous waste SYNTHESIS OF 13C LABELED BROMO ACETIC ACID - S1			
B. EPA Hazardous Waste Code(s) F002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W202
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.8576	*UOM* KILOGRAMS	*Density* 1.32 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.8576
Comments			

GM 314 Waste Characteristics			
A. Description of hazardous waste SULFUR MONOCHLORIDE WASTE			
B. EPA Hazardous Waste Code(s) D002, D003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 6.8946	*UOM* KILOGRAMS	*Density* 1.69 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 6.8946
Comments			

GM 315 Waste Characteristics			
A. Description of hazardous waste 3D PRINTER HEPA VACUUM WATER WITH METAL POWDERS			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G05	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 665.1	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 324.95
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 278.05
Comments			

GM 316 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENT PROCESS (B-1)			
B. EPA Hazardous Waste Code(s) D001, D022, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 9.0718	*UOM* KILOGRAMS	*Density* 0.8 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 9.0718
Comments			

GM 317 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENT WASTE GENERATED FROM EXTRACTIONS, REACTIONS, AND WASHING ORGANIC COMPOUNDS FROM GLASSWARE - BOTTLE #22			
B. EPA Hazardous Waste Code(s) D001, D022, D028, D038, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.5792	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 5.5792
Comments			

GM 318 Waste Characteristics			
A. Description of hazardous waste DEBRIS GR D MTRU BE GT1%			
B. EPA Hazardous Waste Code(s) D004, D005, D006, D007, D008, D009, D010, D011, D018, D019, D021, D022, D035, D038, D039, D040, F001, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 2673.3148
Comments			
1.D VARIOUS LAB OPERATIONS INCLUDING METAL, NITRATE, CHLORIDE, PLUTONIUM, PYROCHEMCIAL OPERATIONS AND PROCESSES			

GM 319 Waste Characteristics

A. Description of hazardous waste

HOMOGENEOUS GR D MTRU BE GT1% SALTS OXIDES ASHES ETC

B. EPA Hazardous Waste Code(s)

D004, D005, D006, D007, D008, D009, D010, D011, D018, D019, D021, D022, D035, D038, D039, D040, F001, F002, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G09		UNITED STATES	W319

F. Waste Minimization Code	*G. Radioactive Mixed*
A	Yes

H. Quantity	*UOM*	*Density*
0.0	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	NM4890139088	H132	36.2874

Comments

1.D VARIOUS LAB OPERATIONS INCLUDING METAL, NITRATE, CHLORIDE, PLUTONIUM, PYROCHEMCIAL OPERATIONS AND PROCESSES; 1.E HOMOGENOUS INORGANIC SOLID MIXTURES ASHES, ALUMINA, CERAMICS, HYDROXIDES, OXALATES, OXIDES AND INORGANIC SALTS

GM 320 Waste Characteristics

A. Description of hazardous waste

BIOTAGE CARTRIDGES USED WITH VARIOUS SOLVENTS

B. EPA Hazardous Waste Code(s)

F002, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G15		UNITED STATES	W319

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
50.122	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	50.122

Comments

1.E CARTRIDGES CONTAINING SILICA

GM 321 Waste Characteristics

A. Description of hazardous waste

MISCELLANEOUS ELECTRONICS AND EQUIPMENT WITH BERYLLIUM

B. EPA Hazardous Waste Code(s)

D006, D007, D008, D010, D011

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G15		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	Yes

H. Quantity	*UOM*	*Density*
850.4858	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	UTD982598898	H132	850.4858

Comments

GM 322 Waste Characteristics

A. Description of hazardous waste

SYNTHESIS OF 13C LABELED BROMO ACETIC ACID - S2

B. EPA Hazardous Waste Code(s)

D001, F003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W203

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
4.8534	KILOGRAMS	1.32 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	4.8534

Comments

GM 323 Waste Characteristics			
A. Description of hazardous waste SYNTHESIS OF 13C LABELED BROMO ACETIC ACID - S3			
B. EPA Hazardous Waste Code(s) F002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W202
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.2205	*UOM* KILOGRAMS	*Density* 1.32 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.2205
Comments			

GM 324 Waste Characteristics			
A. Description of hazardous waste SYNTHESIS OF 13C LABELED BROMO ACETIC ACID - S4			
B. EPA Hazardous Waste Code(s) F002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W202
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.538	*UOM* KILOGRAMS	*Density* 1.32 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.538
Comments			

GM 325 Waste Characteristics

A. Description of hazardous waste

METHANOL/NITRIC ACID HYDROCHLORIC ACID MIXTURE (TIN ETCH)

B. EPA Hazardous Waste Code(s)

D001, D002, F003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G04		UNITED STATES	W203

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
1.4515	KILOGRAMS	1.05 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	1.4515

Comments

GM 326 Waste Characteristics

A. Description of hazardous waste

GENERAL LAB TRASH WITH SOLVENTS, DEGREASERS, EPOXIES

B. EPA Hazardous Waste Code(s)

D008, D011, F002, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
28.8031	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	28.8031

Comments

GM 327 Waste Characteristics			
A. Description of hazardous waste ACIDIC LIQUID LOW LEVEL WASTE			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 2.0412	*UOM* KILOGRAMS	*Density* 1.2 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* FLD980711071	*C. Management Method Code* H121	*D. Total Quantity Shipped* 2.0412
Comments			

GM 328 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK			
B. EPA Hazardous Waste Code(s) D001, D035			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Comments			

GM 329 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK			
B. EPA Hazardous Waste Code(s) D001, D035, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 11.3398	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Comments			

GM 330 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK			
B. EPA Hazardous Waste Code(s) D001, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Comments			

GM 331 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 112.4909	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H061	9.0718

Comments

GM 332 Waste Characteristics			
A. Description of hazardous waste UNUSED/UNSPENT NON-ACUTE RCRA HAZARDOUS/DOT LAB PACK			
B. EPA Hazardous Waste Code(s) D007			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.9072	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Comments			

GM 333 Waste Characteristics			
A. Description of hazardous waste SILVER & GOLD PLATING SOLUTION			
B. EPA Hazardous Waste Code(s) D002, D003, D011, F007			
C. State Hazardous Waste Code(s)			
D. Source Code G03	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W107
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 51.0745	*UOM* KILOGRAMS	*Density* 1.06 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 51.0745
Comments			

GM 334 Waste Characteristics			
A. Description of hazardous waste CONFINEMENT VESSEL DISPOSITION (CVD) MIXED TRU GT1%BE			
B. EPA Hazardous Waste Code(s) D004, D005, D006, D007, D008, D009, D010, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G13	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W304
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 122.1071	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 4186.9438
Comments			

GM 335 Waste Characteristics			
A. Description of hazardous waste METABOLITE EXTRACTION			
B. EPA Hazardous Waste Code(s) D001, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.9685	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 14.9685
Comments			

GM 336 Waste Characteristics			
A. Description of hazardous waste DIESEL FUEL FROM TA-21 CONCRETE CRUSHER			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G13	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W206
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 625.5039	*UOM* KILOGRAMS	*Density* 1.18 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Comments			

GM 337 Waste Characteristics

A. Description of hazardous waste

SOLUTIONS OF CONCENTRATED HYDROGEN PEROXIDE, 70 - 90%.

B. EPA Hazardous Waste Code(s)

D001, D002

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W119

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
9.3894	KILOGRAMS	1.4 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	9.3894

Comments

1.E CONCENTRATED HYDROGEN PEROXIDE SOLUTION

GM 338 Waste Characteristics

A. Description of hazardous waste

INERT SIMULANT (900-21) CONSISTING OF BARIUM NITRATE

B. EPA Hazardous Waste Code(s)

D005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W319

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
125.6451	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	125.6451

Comments

1.E INERT SOLIDS CONTAINING PLASTICIZERS, BINDERS AND BARIUM NITRATE

GM 339 Waste Characteristics			
A. Description of hazardous waste DEBRIS GR B MTRU BE GT1%			
B. EPA Hazardous Waste Code(s) D005, D006, D007, D008, D009, D010, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 5.1256	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 2109.5131
Comments			
1.D GENERAL HOUSEKEEPING AND ROUTINE MAINTAINANCE			

GM 340 Waste Characteristics			
A. Description of hazardous waste HOMOGENEOUS GR B MTRU BE GT1% SALTS OXIDES ASHES ETC.			
B. EPA Hazardous Waste Code(s) D005, D006, D007, D008, D009, D010, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W319
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 63.7754
Comments			
1.D VARIOUS LAB OPERATIONS INCLUDING METAL, NITRATE, CHLORIDE, PLUTONIUM, PYROCHEMCIAL OPERATIONS AND PROCESSES; 1.E HOMOGENOUS INORGANIC SOLID MIXTURES ASHES, ALUMINA, CERAMICS, HYDROXIDES, OXALATES, OXIDES AND INORGANIC SALTS			

GM 341 Waste Characteristics

A. Description of hazardous waste

ORGANIC SOLVENT WASTE GENERATED FROM CHROMATOGRAPHY BIOTAGE

B. EPA Hazardous Waste Code(s)

D001, F002, F003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W204

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
5.1256	KILOGRAMS	0.88 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	5.1256

Comments

GM 342 Waste Characteristics

A. Description of hazardous waste

LEAD PAINT CHIPS AND PPE

B. EPA Hazardous Waste Code(s)

D006, D007, D008

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G13		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
7.7111	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	7.7111

Comments

GM 343 Waste Characteristics

A. Description of hazardous waste

SCRAP METAL, EQUIPMENT AND MACHINERY WITH HIGH EXPLOSIVE (HE) CONTAMINATION

B. EPA Hazardous Waste Code(s)

D003, D030

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G15		UNITED STATES	W307

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
798.55	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

	Management Method Code	*Quantity*
Process System 1	H129	798.55

Off-site Shipment of Hazardous Waste

Comments

GM 344 Waste Characteristics

A. Description of hazardous waste

NITRIC ACID PASSIVATION SOLUTION (50% WATER/50% NITRIC ACID)

B. EPA Hazardous Waste Code(s)

D002

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G01		UNITED STATES	W103

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
51.9817	KILOGRAMS	1.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	51.9817

Comments

GM 345 Waste Characteristics			
A. Description of hazardous waste GENERAL LAB TRASH CONTAINING BARIUM,CHROMIUM, SILVER, & CADNIUM COMPOUNDS.			
B. EPA Hazardous Waste Code(s) D005, D006, D007, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 7.2575	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 7.2575
Comments			

GM 346 Waste Characteristics			
A. Description of hazardous waste AMMONIUM PERSULFATE ETCH SOLUTION			
B. EPA Hazardous Waste Code(s) D001, D002			
C. State Hazardous Waste Code(s)			
D. Source Code G04	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W105
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.5338	*UOM* KILOGRAMS	*Density* 1.1 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.5338
Comments			

GM 347 Waste Characteristics			
A. Description of hazardous waste MIXTURE OF ETHYL ETHER AND HYDROCHLORIC ACID CONTAINING BARIUM,CHROMIUM, SILVER, CADMIUM, LEAD, & MERCURY COMPOUNDS.			
B. EPA Hazardous Waste Code(s) D001, D002, D005, D006, D007, D008, D009, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 6.3503	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* FLD980711071	*C. Management Method Code* H061	*D. Total Quantity Shipped* 6.3503
Comments			

GM 348 Waste Characteristics			
A. Description of hazardous waste GENERAL LAB TRASH CONTAINING BARIUM,CHROMIUM, SILVER, CADMIUM, LEAD, & MERCURY			
B. EPA Hazardous Waste Code(s) D005, D006, D007, D008, D009, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 9.0718	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 9.0718
Comments			

GM 349 Waste Characteristics			
A. Description of hazardous waste NITRIC ACID/WATER SOLUTION USED FOR CLEANING STAINLESS STEEL COUPONS			
B. EPA Hazardous Waste Code(s) D002, D007			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.8555	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.8555
Comments			

GM 350 Waste Characteristics			
A. Description of hazardous waste SPENT FERRIC CHLORIDE ETCHANT AND WATER WITH PH GT 2			
B. EPA Hazardous Waste Code(s) D002, D007			
C. State Hazardous Waste Code(s)			
D. Source Code G04	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W105
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 6032.7789	*UOM* KILOGRAMS	*Density* 2.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 6032.7789
Comments			

GM 351 Waste Characteristics			
A. Description of hazardous waste RECIRCULATING WATER FROM TA-22 ETCHING SHOP TANK PH 12.5			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G13	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W110
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 202.3022	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 202.3022
Comments			

GM 352 Waste Characteristics			
A. Description of hazardous waste RECIRCULATING WATER FROM TA-22 ETCHING SHOP TANK PH GT2			
B. EPA Hazardous Waste Code(s) D002, D007			
C. State Hazardous Waste Code(s)			
D. Source Code G13	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W105
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 203.2094	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 203.2094
Comments			

GM 353 Waste Characteristics			
A. Description of hazardous waste HIGH PRESSURE LIQUID CHROMOTOGRAPHY PROCESS			
B. EPA Hazardous Waste Code(s) D001, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W119
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 53.2971	*UOM* KILOGRAMS	*Density* 0.85 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 53.2971
Comments			
1.E METHANOL SOLUTION			

GM 354 Waste Characteristics			
A. Description of hazardous waste PROCESS USED TO PRESERVE AND ANALYZE AQUEOUS FIELD SAMPLES THAT MAY CONTAIN SULFIDE.			
B. EPA Hazardous Waste Code(s) D002, D003, D008			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W110
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 10.6594	*UOM* KILOGRAMS	*Density* 2.13 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 10.6594
Comments			

GM 355 Waste Characteristics			
A. Description of hazardous waste HACH TEST KITS 8507,8155,8146,8008,8023,8024,8185 AND 8131			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W105
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 25.4012	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Comments			

GM 356 Waste Characteristics			
A. Description of hazardous waste HACH TEST KIT 8171			
B. EPA Hazardous Waste Code(s) D006			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W105
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 25.4012	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Comments			

GM 357 Waste Characteristics			
A. Description of hazardous waste HACH TEST KIT 14388-01 AND R-42 WATER			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W001
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.8144	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Comments			

GM 358 Waste Characteristics			
A. Description of hazardous waste LIQUID SAMPLE WASTE			
B. EPA Hazardous Waste Code(s) D001, D018, D021, D022, D027, D028, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 20.3209	*UOM* KILOGRAMS	*Density* 0.8 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 20.3209
Comments			

GM 359 Waste Characteristics			
A. Description of hazardous waste SPENT GLOVEBOX CATALYST			
B. EPA Hazardous Waste Code(s) D018, D028, D039, D040			
C. State Hazardous Waste Code(s)			
D. Source Code G08	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W310
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 9.0718	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 9.0718
Comments			

GM 360 Waste Characteristics			
A. Description of hazardous waste RLW LINE REPAIRS			
B. EPA Hazardous Waste Code(s) D008			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 42.3655	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 42.3655
Comments			

GM 361 Waste Characteristics			
A. Description of hazardous waste REVERSING SWITCH DECOMMISSIONING			
B. EPA Hazardous Waste Code(s) D011			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 268.5267	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 268.5267
Comments			

GM 362 Waste Characteristics			
A. Description of hazardous waste REMOVAL OF LEAD (ITEMS/PIECES) BELOW SINK OR FROM DRAIN PIPE.			
B. EPA Hazardous Waste Code(s) D008			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W307
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 1199.2983	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 1199.2983
Comments			

GM 363 Waste Characteristics			
A. Description of hazardous waste AQUEOUS WASTE GENERATED FROM EXTRACTIONS, REACTIONS, AND WASHING ORGANIC COMPOUNDS FROM GLASSWARE-7			
B. EPA Hazardous Waste Code(s) D007, F002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W119
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 6.4954	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 6.4954
Comments			
1.E LABORATORY EXPERIMENT WASTE CONTAINING IGNITABLE SOLVENTS			

GM 364 Waste Characteristics			
A. Description of hazardous waste A107-W1			
B. EPA Hazardous Waste Code(s) D001, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 17.0097	*UOM* KILOGRAMS	*Density* 0.98 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 17.0097
Comments			

GM 365 Waste Characteristics			
A. Description of hazardous waste 60% METHANOL-REAGENT GRADE-40% 6.25N NAOH SOLUTION. SOLUTION IS USED AS AN ETCHANT ON NEUTRON DETECTORS			
B. EPA Hazardous Waste Code(s) D001, D002			
C. State Hazardous Waste Code(s)			
D. Source Code G04	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W110
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 97.5224	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 97.5224
Comments			

GM 366 Waste Characteristics			
A. Description of hazardous waste CIN01 WASTE CONTAINERS			
B. EPA Hazardous Waste Code(s) D004, D005, D006, D007, D008, D009, D010, D011, D018, D019, D021, D022, D035, D038, D039, D040, F001, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W319
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* NM4890139088	*C. Management Method Code* H132	*D. Total Quantity Shipped* 13930.9312
Comments			
1.D REPACKAGING OPERATIONS FOR TRANSURANIC WASTE; 1.E CEMENTED TRANSURANIC WASTE			

GM 367 Waste Characteristics			
A. Description of hazardous waste VACUUM FURNACE COOLING WATER			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G13	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W105
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 117.9794	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 117.9794
Comments			

GM 368 Waste Characteristics			
A. Description of hazardous waste PEPTIDE SYNTHESIS, CLEAVAGE, AND PRECIPITATION			
B. EPA Hazardous Waste Code(s) D001, D002, F002, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 33.2937	*UOM* KILOGRAMS	*Density* 1.1 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 33.2937
Comments			

GM 369 Waste Characteristics			
A. Description of hazardous waste ACRYLATE AND CERAMIC FROM UV CURABLE PRINTING			
B. EPA Hazardous Waste Code(s) D001, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W219
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 19.6859	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 19.6859
Comments			
1.E LABORATORY EXPERIMENT WASTE CONTAINING IGNITABLE SOLVENTS			

GM 370 Waste Characteristics			
A. Description of hazardous waste SOLID WASTE FROM GOLD REFINING PROCESS			
B. EPA Hazardous Waste Code(s) D001, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W316
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.5401	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.5401
Comments			

GM 371 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENTS WASTE			
B. EPA Hazardous Waste Code(s) D001, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 22.4528	*UOM* KILOGRAMS	*Density* 0.95 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 22.4528
Comments			

GM 372 Waste Characteristics			
A. Description of hazardous waste USED CHROMATOGRAPHY SOLVENTS - DICHLOROMETHANE AND METHANOL			
B. EPA Hazardous Waste Code(s) D001, F002, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 40.0976	*UOM* KILOGRAMS	*Density* 1.33 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 40.0976
Comments			

GM 373 Waste Characteristics			
A. Description of hazardous waste TA-16-399 BURN TRAY CLOSURE			
B. EPA Hazardous Waste Code(s) D003			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W307
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 63.52	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Process System 1	*Management Method Code* H129	*Quantity* 63.52	
Off-site Shipment of Hazardous Waste			
Comments			
1D. FLASHING OF HE CONTAMINATED BURN TRAY			

GM 374 Waste Characteristics

A. Description of hazardous waste

SILVER & GOLD PLATING SOLUTION CLEAN-UP TOWELS

B. EPA Hazardous Waste Code(s)

D011, F007, D003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G03		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
2.4494	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	2.4494

Comments

GM 375 Waste Characteristics

A. Description of hazardous waste

LEAD SOLIDS AND LEAD CONTAMINATED MATERIALS FROM ROUTINE HOUSEKEEPING AND MAINTENANCE OPERATIONS

B. EPA Hazardous Waste Code(s)

D008

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G19		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	Yes

H. Quantity	*UOM*	*Density*
2349.155	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	UTD982598898	H132	2349.155

Comments

1.D ROUTINE MAINTENANCE AND HOUSEKEEPING

GM 376 Waste Characteristics			
A. Description of hazardous waste CONCRETE WATER			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W110
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 79.6055	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 79.6055
Comments			
1.D RINSATE FROM CONCRETE CUTTING OPERATIONS			

GM 377 Waste Characteristics			
A. Description of hazardous waste MATERIAL TRANSFER PROJECT POLYMER WASTE			
B. EPA Hazardous Waste Code(s) F002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W403
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 28.8485	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 28.8485
Comments			

GM 378 Waste Characteristics			
A. Description of hazardous waste LABORATORY TRASH FROM THE SYNTHESIS AND PURIFICATION OF ORGANIC AND INORGANIC COMPLEXES.			
B. EPA Hazardous Waste Code(s) F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 12.9274	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 12.9274
Comments			

GM 379 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENT WASTE GENERATED FROM EXTRACTIONS, REACTIONS, AND WASHING ORGANIC COMPOUNDS FROM GLASSWARE - BOTTLE #24			
B. EPA Hazardous Waste Code(s) D001, D018, D022, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.2163	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 5.2163
Comments			

GM 380 Waste Characteristics			
A. Description of hazardous waste USED CHROMATOGRAPHY SOLVENTS - DICHLOROMETHANE AND METHANOL (YURI)			
B. EPA Hazardous Waste Code(s) D001, F002, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 44.9056	*UOM* KILOGRAMS	*Density* 1.33 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 19.0509
Comments			

GM 381 Waste Characteristics			
A. Description of hazardous waste SPENT SOLVENT (USED FOR CLEANING EQUIPMENT DURING PAINT OPERATIONS)			
B. EPA Hazardous Waste Code(s) D001, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G06	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 962.7952	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 800.4091
Comments			

GM 382 Waste Characteristics			
A. Description of hazardous waste ALKALINE PLANT EXTRACT			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W110
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.4473	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.4473
Comments			

GM 383 Waste Characteristics			
A. Description of hazardous waste HAZARDOUS WASTE CYLINDERS-NOT DESTINED FOR GAS PLANT			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G11	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W801
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.0907	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.0907
Comments			

GM 384 Waste Characteristics			
A. Description of hazardous waste TA3-0038 USED OIL			
B. EPA Hazardous Waste Code(s) D018, D022, D040			
C. State Hazardous Waste Code(s)			
D. Source Code G16	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W206
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 186.5172	*UOM* KILOGRAMS	*Density* 0.93 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 186.5172
Comments			

GM 385 Waste Characteristics			
A. Description of hazardous waste SPENT, EMPTIED OIL FILTERS GENERATED AT TA-21, REMOVED FROM LEFTOVER EQUIPMENT			
B. EPA Hazardous Waste Code(s) D008			
C. State Hazardous Waste Code(s)			
D. Source Code G16	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W310
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 55.5651	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Comments			

GM 386 Waste Characteristics			
A. Description of hazardous waste ALKALINITY AND SULFIDE TITRATIONS			
B. EPA Hazardous Waste Code(s) D002, D007			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.9009	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.9009
Comments			

GM 387 Waste Characteristics			
A. Description of hazardous waste CR 6+ ELECTRO-CHEMICAL REDUCTION			
B. EPA Hazardous Waste Code(s) D007			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.0865	*UOM* KILOGRAMS	*Density* 1.2 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.0865
Comments			

GM 388 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENT WASTE GENERATED FROM EXTRACTIONS, REACTIONS, AND WASHING ORGANIC COMPOUNDS FROM GLASSWARE - BOTTLE #23			
B. EPA Hazardous Waste Code(s) D001, D022, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.1256	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.1256
Comments			

GM 389 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENT WASTE GENERATED FROM CHROMATOGRAPHY - BIOTAGE NORMAL PHASE MEOH/ DCM			
B. EPA Hazardous Waste Code(s) D001, F002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 12.0837	*UOM* KILOGRAMS	*Density* 1.1 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 7.8471
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 4.2366
Comments			

GM 390 Waste Characteristics			
A. Description of hazardous waste (HG 0-1.5PPM) NANOPARTICLE SYNTHESIS, SURFACE MODIFICATION, FILM DEPOSITION, AND SAMPLE PREPARATION ORGANIC LIQUID WASTE			
B. EPA Hazardous Waste Code(s) D001, D004, D005, D006, D008, D010, D011, D018, D019, D021, D022, D028, D035, D038, D039, D040, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 268.0731	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 43.7717
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 224.3014
Comments			
1.D SYNTHESIS OF NANOPARTICLES			

GM 391 Waste Characteristics			
A. Description of hazardous waste ACID WASTE FROM CHEMICAL REACTIONS #2			
B. EPA Hazardous Waste Code(s) D002, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.9958	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.9958
Comments			

GM 392 Waste Characteristics			
A. Description of hazardous waste CLEAN UP MATERIAL FROM SPILL OF 102 SBS ADHESIVE LABEL			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G32	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W219
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 89.3123	*UOM* KILOGRAMS	*Density* 1.15 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 89.3123
Comments			
1.E ADHESIVES, ASPHALT, GRAVEL, SAND			

GM 393 Waste Characteristics			
A. Description of hazardous waste CS2, NAN3 NANOPARTICLE SYNTHESIS, SURFACE MODIFICATION, FILM DEPOSITION, AND SAMPLE PREPARATION ORGANIC LIQUID WASTE			
B. EPA Hazardous Waste Code(s) D001, D004, D005, D006, D008, D010, D011, D018, D019, D021, D022, D028, D035, D038, D039, D040, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.0412	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.0412
Comments			
1.D SYNTHESIS OF NANOPARTICLES			

GM 394 Waste Characteristics			
A. Description of hazardous waste CS2, NAN3 NANOPARTICLE SYNTHESIS, SURFACE MODIFICATION, FILM DEPOSITION, AND SAMPLE PREPARATION SOLID WASTE			
B. EPA Hazardous Waste Code(s) D001, D004, D005, D006, D008, D010, D011, D019, D021, D022, D028, D035, D038, D039, D040, F002, F003, F005, P022, P105			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.6804	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.6804
Comments			
1.D SYNTHESIS OF NANOPARTICLES			

GM 395 Waste Characteristics			
A. Description of hazardous waste PALLADIUM ON CARBON ON SYRINGE FILTERS SUBMERGED IN WATER			
B. EPA Hazardous Waste Code(s) D001, D003			
C. State Hazardous Waste Code(s)			
D. Source Code G08	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W119
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.5987	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.5987
Comments			
1.E PALLADIUM ON CARBON IN WATER			

GM 396 Waste Characteristics			
A. Description of hazardous waste MLLW USED OIL FROM PRESS BUILDING			
B. EPA Hazardous Waste Code(s) D008			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W205
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 3230.2129	*UOM* KILOGRAMS	*Density* 0.87 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H134	*D. Total Quantity Shipped* 3230.2129
Comments			

GM 397 Waste Characteristics			
A. Description of hazardous waste AQUEOUS WASTE GENERATED FROM EXTRACTIONS, REACTIONS, AND WASHING ORGANIC COMPOUNDS FROM GLASSWARE-8			
B. EPA Hazardous Waste Code(s) D007, F002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W119
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.1256	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.1256
Comments			
1.E NON-FLAMMABLE AQUEOUS WASTE CONTAMINATED WITH SOLVENTS			

GM 398 Waste Characteristics			
A. Description of hazardous waste ORGANIC SOLVENT WASTE GENERATED FROM EXTRACTIONS, REACTIONS, AND WASHING ORGANIC COMPOUNDS FROM GLASSWARE - BOTTLE #25			
B. EPA Hazardous Waste Code(s) D001, D018, D022, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W204
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.8967	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.8967
Comments			

GM 399 Waste Characteristics			
A. Description of hazardous waste ACID WASTE FROM CHEMICAL REACTIONS #3			
B. EPA Hazardous Waste Code(s) D002, D007, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.8758	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.8758
Comments			

GM 400 Waste Characteristics

A. Description of hazardous waste

LAB TRASH DERIVED FROM THE SYNTHESIS AND PURIFICATION OF ORGANIC AND INORGANIC COMPLEXES.

B. EPA Hazardous Waste Code(s)

D001, D007, D022, F002, F003, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G09		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
12.247	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	12.247

Comments

1.D ROUTINE MAINTENANCE AND HOUSEKEEPING

GM 401 Waste Characteristics

A. Description of hazardous waste

SHREDDED ELECTRONIC MEDIA CLAEAN UP

B. EPA Hazardous Waste Code(s)

D004

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G19		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
665.0	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	665.0

Comments

1.D ROUTINE MAINTENANCE AND HOUSEKEEPING

GM 402 Waste Characteristics			
A. Description of hazardous waste PEEL AWAY 7 - PAINT REMOVAL			
B. EPA Hazardous Waste Code(s) D008			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 444.5206	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD991300484	*C. Management Method Code* H132	*D. Total Quantity Shipped* 444.5206
Comments			
1.D ROUTINE MAINTENANCE AND HOUSEKEEPING			

GM 403 Waste Characteristics			
A. Description of hazardous waste CHROMIUM PLATING BATH			
B. EPA Hazardous Waste Code(s) D001, D002, D004, D006, D007, D008, D010			
C. State Hazardous Waste Code(s)			
D. Source Code G03	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 657.5	*UOM* KILOGRAMS	*Density* 1.3 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H134	*D. Total Quantity Shipped* 657.5
Comments			

GM 404 Waste Characteristics			
A. Description of hazardous waste CHROMIC ACID/SULFURIC ACID ELECTROPOLISH			
B. EPA Hazardous Waste Code(s) D001, D002, D004, D006, D007, D008, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G04	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 1720.5	*UOM* KILOGRAMS	*Density* 1.3 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 1720.5
Comments			

GM 405 Waste Characteristics			
A. Description of hazardous waste PALLADIUM ON CARBON SUBMERGED IN WATER			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 0.9979	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 0.9979
Comments			

GM 406 Waste Characteristics			
A. Description of hazardous waste NANOPARTICLES SYNTHESIS ACIDIC AQUEOUS WASTE WITH TRACE AMOUNTS OF UNBOUND NANOPARTICLES			
B. EPA Hazardous Waste Code(s) D001, D002, D006, D008, D009, D010, D011, D022, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 17.2365	*UOM* KILOGRAMS	*Density* 0.9 sg	

On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 17.2365
Comments			

GM 407 Waste Characteristics			
A. Description of hazardous waste NANOPARTICLE SYNTHESIS, SURFACE MODIFICATION, FILM DEPOSITION, AND SAMPLE PREPARATION SOLID WASTE			
B. EPA Hazardous Waste Code(s) D001, D004, D005, D006, D008, D009, D010, D011, D019, D021, D022, D028, D035, D038, D039, D040, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 129.2738	*UOM* KILOGRAMS	*Density* 0.0 sg	

On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 129.2738
Comments			
1.D SYNTHESIS OF NANOPARTICLES			

GM 408 Waste Characteristics			
A. Description of hazardous waste HE CONTAMINATED SCRAP METAL			
B. EPA Hazardous Waste Code(s) D003, D030			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W307
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 108.89	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Process System 1	*Management Method Code* H129	*Quantity* 108.89	
Off-site Shipment of Hazardous Waste			
Comments			
1.D FLASHING OF HE CONTAMINATED SCRAP METAL AND EQUIPMENT			

GM 409 Waste Characteristics			
A. Description of hazardous waste TA59_ELECTROCHEMICAL ACTIVITIES AND AMALGAMATION OF TRANSITION METALS AND LANTHANIDES			
B. EPA Hazardous Waste Code(s) D009			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 7.0307	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 7.0307
Comments			

GM 410 Waste Characteristics			
A. Description of hazardous waste TA59_ELECTROCHEMICAL ACTIVITIES INVOLVING STRONG OXIDIZERS AND ACIDS			
B. EPA Hazardous Waste Code(s) D001, D002, D009			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W105
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 6.3503	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 6.3503
Comments			

GM 411 Waste Characteristics			
A. Description of hazardous waste ULTRASONIC CLEANING WITH MINERAL OIL			
B. EPA Hazardous Waste Code(s) D006			
C. State Hazardous Waste Code(s)			
D. Source Code G08	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 766.8433	*UOM* KILOGRAMS	*Density* 1.1 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 766.8433
Comments			

GM 412 Waste Characteristics			
A. Description of hazardous waste CERIUM CHIPS WITH CLASS D DRY POWDER			
B. EPA Hazardous Waste Code(s) D001, D003			
C. State Hazardous Waste Code(s)			
D. Source Code G32	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W319
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 4.7627	*UOM* KILOGRAMS	*Density* 0.0 sg	

On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 4.7627
Comments			
1.E POWDER FROM EXTINGUISHER WITH CERIUM CHIPS			

GM 413 Waste Characteristics			
A. Description of hazardous waste HE MACHINING OPERATIONS AT TA-16-260			
B. EPA Hazardous Waste Code(s) D003, D030			
C. State Hazardous Waste Code(s)			
D. Source Code G09	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W405
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 240.47	*UOM* KILOGRAMS	*Density* 0.0 sg	

On-site Generation and Management of Hazardous Waste			
Process System 1	*Management Method Code* H129	*Quantity* 240.47	
Off-site Shipment of Hazardous Waste			
Comments			
1.D HE MACHINING OPERATIONS			

GM 414 Waste Characteristics

A. Description of hazardous waste

SCRAP METAL, EQUIPMENT AND MACHINERY WITH HIGH EXPLOSIVE (HE) CONTAMINATION

B. EPA Hazardous Waste Code(s)

D003, D030

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G15		UNITED STATES	W307

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
326.68	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

	Management Method Code	*Quantity*
Process System 1	H129	326.68

Off-site Shipment of Hazardous Waste

Comments

GM 415 Waste Characteristics

A. Description of hazardous waste

ELECTRONICS AND COPPER WITH SOLDER CONTAMINATED WITH URANIUM FROM EQUIPMENT REMOVAL OPERATIONS

B. EPA Hazardous Waste Code(s)

D008, D011

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G15		UNITED STATES	W320

F. Waste Minimization Code	*G. Radioactive Mixed*
A	Yes

H. Quantity	*UOM*	*Density*
3831.0414	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	UTD982598898	H132	3831.0414

Comments

GM 416 Waste Characteristics			
A. Description of hazardous waste ALODINE DIP TANK			
B. EPA Hazardous Waste Code(s) D001, D006, D007			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 492.1478	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 492.1478
Comments			

GM 417 Waste Characteristics			
A. Description of hazardous waste MATERIALS AND ACID FROM CLEANING ACID SPILL			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G32	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 9.7522	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 9.7522
Comments			

GM 418 Waste Characteristics			
A. Description of hazardous waste CHROMIC ACID TANKS AND EQUIPMENT			
B. EPA Hazardous Waste Code(s) D001, D004, D006, D007, D008, D010, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 4191.6474	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 4191.6474
Comments			

GM 419 Waste Characteristics			
A. Description of hazardous waste MISCELLANEOUS ELECTRONICS POTENTIAL INTERNAL RADIOACTIVE CONTAMINATION			
B. EPA Hazardous Waste Code(s) D006, D008, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 404.6044	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 404.6044
Comments			

GM 420 Waste Characteristics			
A. Description of hazardous waste CYANIDE TANK AND EQUIPMENT			
B. EPA Hazardous Waste Code(s) D003			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 918.5246	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 918.5246
Comments			

GM 421 Waste Characteristics			
A. Description of hazardous waste DEBRIS FROM LEAD PAINT REMOVAL AT TA-14-6			
B. EPA Hazardous Waste Code(s) D008			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 52.8889	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 52.8889
Comments			
1.D HEAVY METAL PAINT REMOVAL			

GM 422 Waste Characteristics			
A. Description of hazardous waste ACIDIC ELECTROPOLISHING SOLUTION			
B. EPA Hazardous Waste Code(s) D002, D007			
C. State Hazardous Waste Code(s)			
D. Source Code G02	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 6.6224	*UOM* KILOGRAMS	*Density* 1.15 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 6.6224
Comments			

GM 423 Waste Characteristics			
A. Description of hazardous waste METABOLITE EXTRACTION			
B. EPA Hazardous Waste Code(s) D001, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 9.0718	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 9.0718
Comments			

GM 424 Waste Characteristics			
A. Description of hazardous waste MISCELLANEOUS ELECTRONICS AND LIGHTING COMPONENTS			
B. EPA Hazardous Waste Code(s) D006, D007, D008, D009, D010, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W320
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H141	*D. Total Quantity Shipped* 14.515
Comments			
1.D ROUTINE MAINTENANCE AND HOUSEKEEPING			

GM 425 Waste Characteristics			
A. Description of hazardous waste GASOLINE SOAKED RAGS			
B. EPA Hazardous Waste Code(s) D001, D018			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 0.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 5.8967
Comments			

GM 426 Waste Characteristics

A. Description of hazardous waste

USED CHN COLUMNS

B. EPA Hazardous Waste Code(s)

D007, D011

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
2.268	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	2.268

Comments

GM 427 Waste Characteristics

A. Description of hazardous waste

SOLVENT WASTE FROM NANOPARTICLE SYNTHESIS, ARRAYS, COMPOSITE MATERIALS & SURFACE MODIFICATION

B. EPA Hazardous Waste Code(s)

D001, D003, D004, D005, D006, D007, D008, D010, D011, D018, D019, D021, D022, D026, D028, D029, D035, D036, D038, D039, D040, F002, F003, F004, F005

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W204

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
23.5868	KILOGRAMS	0.9 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

Site 1	*B. EPA ID of facility to which waste was shipped*	*C. Management Method Code*	*D. Total Quantity Shipped*
	COD980591184	H141	23.5868

Comments

GM 428 Waste Characteristics			
A. Description of hazardous waste SODIUM HYDROXIDE USED FOR ETCHANT/CLEANING IN ELECTROPLATING PROCESS			
B. EPA Hazardous Waste Code(s) D002, D007			
C. State Hazardous Waste Code(s)			
D. Source Code G04	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W110
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 11.5212	*UOM* KILOGRAMS	*Density* 1.12 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 11.5212
Comments			

GM 429 Waste Characteristics			
A. Description of hazardous waste HNO3 AND HF ETCHANT			
B. EPA Hazardous Waste Code(s) D002, D007			
C. State Hazardous Waste Code(s)			
D. Source Code G04	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 16.6922	*UOM* KILOGRAMS	*Density* 1.15 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 16.6922
Comments			

GM 430 Waste Characteristics

A. Description of hazardous waste

ELECTROLESS COPPER SOLUTION

B. EPA Hazardous Waste Code(s)

D002, D003

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W107

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
6.5317	KILOGRAMS	1.1 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	6.5317

Comments

GM 431 Waste Characteristics

A. Description of hazardous waste

SILVER CONTAINING POLYMER WASTE

B. EPA Hazardous Waste Code(s)

D011

C. State Hazardous Waste Code(s)

D. Source Code	*Management Method Code*	*Country*	*E. Form Code*
G22		UNITED STATES	W002

F. Waste Minimization Code	*G. Radioactive Mixed*
A	No

H. Quantity	*UOM*	*Density*
2.7216	KILOGRAMS	0.0 sg

On-site Generation and Management of Hazardous Waste

Off-site Shipment of Hazardous Waste

	B. EPA ID of facility to which waste was shipped	*C. Management Method Code*	*D. Total Quantity Shipped*
Site 1	COD980591184	H141	2.7216

Comments

GM 432 Waste Characteristics			
A. Description of hazardous waste			
LAB TRASH: SOLVENTS/ METALS/ REACTIVES FROM NANOPARTICLE SYNTHESIS, ARRAYS, COMPOSITE MATERIALS & SURFACE MODIFICATION			
B. EPA Hazardous Waste Code(s)			
D003, D004, D005, D006, D007, D008, D010, D011, D018, D019, D021, D022, D026, D028, D029, D035, D036, D038, D039, D040, F002, F004, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.8778	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 14.8778
Comments			

GM 433 Waste Characteristics			
A. Description of hazardous waste			
HACH TEST KIT 8131, 8146, AND 8023 SOLUTION / HAZ			
B. EPA Hazardous Waste Code(s)			
D002, D007			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W105
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 16.3293	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Comments			

GM 434 Waste Characteristics			
A. Description of hazardous waste CONATHANE EN-4 AND EN-7 CONTAMINATED WASTE MATERIAL FROM THE SOLDERING AND POTTING SUPPLY CONNECTOR PROCESS			
B. EPA Hazardous Waste Code(s) D003, U223			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 6.0555	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 4.7627
Comments			
1.D SOLDERING OPERATIONS			

GM 435 Waste Characteristics			
A. Description of hazardous waste MERCURY CONTAMINATED MLLW, FP-15 SHUTTER SYSTEM REMOVED FROM SERVICE			
B. EPA Hazardous Waste Code(s) D009			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 1959.9728	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 1959.9728
Comments			

GM 436 Waste Characteristics			
A. Description of hazardous waste SOLVENT VAPOR CONTAMINATED COPPER CATALYST AND MOLECULAR SIEVE REMOVED FROM GLOVE BOX AIR DRIER FILTER CANISTER			
B. EPA Hazardous Waste Code(s) D005, D007, D028, D038, D039, D040			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W310
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 61.0082	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 61.0082
Comments			
1.D GLOVEBOX FILTER CHANGEOUT			

GM 437 Waste Characteristics			
A. Description of hazardous waste SILICOMOLYBDATE METHOD - LIQUID WASTE			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 5.2163	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 5.2163
Comments			

GM 438 Waste Characteristics			
A. Description of hazardous waste SYNTHESIS OF POLYMERS,IONIC LIQUIDS & ORGANIC EXTENDED SOLIDS 1420-1221			
B. EPA Hazardous Waste Code(s) D006, D010, F002, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 23.4054	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 23.4054
Comments			

GM 439 Waste Characteristics			
A. Description of hazardous waste ELECTRONICS AND COPPER WITH SOLDER CONTAMINATED WITH URANIUM AND BERYLLIUM FROM EQUIPMENT REMOVAL OPERATIONS			
B. EPA Hazardous Waste Code(s) D008, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W320
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 523.8992	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 523.8992
Comments			

GM 440 Waste Characteristics			
A. Description of hazardous waste MIXED AQUEOUS ALKALINE WASTE			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W119
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 3.2205	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.2205
Comments			
1.E DILUTE AMMONIUM HYDROXIDE SOLUTION			

GM 441 Waste Characteristics			
A. Description of hazardous waste HF WASTE			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W103
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.3608	*UOM* KILOGRAMS	*Density* 1.06 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.3608
Comments			

GM 442 Waste Characteristics			
A. Description of hazardous waste MERCURY AND MERCURY SALTS ON GLASSWARE			
B. EPA Hazardous Waste Code(s) D009			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.6329	*UOM* KILOGRAMS	*Density* 13.56 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.6329
Comments			

GM 443 Waste Characteristics			
A. Description of hazardous waste MLLW SOIL AND DEBRIS GENERATED FROM ACTIVITIES AT THE TA-15 R-44 FIRING SITE			
B. EPA Hazardous Waste Code(s) D008			
C. State Hazardous Waste Code(s)			
D. Source Code G44	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W301
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 1360340.3905	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* UTD982598898	*C. Management Method Code* H132	*D. Total Quantity Shipped* 1091412.2604
Comments			

GM 444 Waste Characteristics			
A. Description of hazardous waste SCRAP METAL, QUIPMENT AND MACHINERY WITH HIGH EXPLOSIVE (HE) CONTAMINATION			
B. EPA Hazardous Waste Code(s) D003, D030			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 36.3	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Process System 1	*Management Method Code* H129	*Quantity* 36.3	
Off-site Shipment of Hazardous Waste			
Comments			

GM 445 Waste Characteristics			
A. Description of hazardous waste HAZARDOUS LIQUID WASTE GENERATED IN PARTICLE CHEMISTRY 2			
B. EPA Hazardous Waste Code(s) D001, D011, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W113
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 20.8653	*UOM* KILOGRAMS	*Density* 0.98 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 20.8653
Comments			

GM 446 Waste Characteristics			
A. Description of hazardous waste LAB TRASH HAZARDOUS WASTE GENERATED IN PARTICLE CHEMISTRY 2			
B. EPA Hazardous Waste Code(s) D001, D011, D022, D027, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 7.9379	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 7.9379
Comments			

GM 447 Waste Characteristics			
A. Description of hazardous waste TA-8-70 PAINT CHIPS & WASTE			
B. EPA Hazardous Waste Code(s) D008, D009			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 2.268	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 2.268
Comments			
1.D HEAVY METAL PAINT REMOVAL			

GM 448 Waste Characteristics			
A. Description of hazardous waste HEPA VAC			
B. EPA Hazardous Waste Code(s) D008			
C. State Hazardous Waste Code(s)			
D. Source Code G15	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 14.515	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 14.515
Comments			

GM 449 Waste Characteristics			
A. Description of hazardous waste SOLID WASTE GENERATED IN THE SYNTHESIS, PURIFICATION, AND SAMPLE PREP OF INORGANIC/ORGANOMETALLIC COMPOUNDS C143			
B. EPA Hazardous Waste Code(s) D007, D008, D011, F002, F004, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 10.7955	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 10.7955
Comments			

GM 450 Waste Characteristics			
A. Description of hazardous waste RADAR TRAILER- METAL BASED PAINT ON WOOD			
B. EPA Hazardous Waste Code(s) D005, D006, D007, D008			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 238.0	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 238.0
Comments			
1.D HEAVY METAL PAINT REMOVAL			

GM 451 Waste Characteristics			
A. Description of hazardous waste WASTE RAGS GENERATED DURING PAINTING OPERATIONS			
B. EPA Hazardous Waste Code(s) D001, F002, F003, F005			
C. State Hazardous Waste Code(s)			
D. Source Code G06	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 88.4505	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Comments			

GM 452 Waste Characteristics			
A. Description of hazardous waste ACIDIC AQUEOUS SOLUTION FOR ANALYSIS ICP-MS/OES			
B. EPA Hazardous Waste Code(s) D002			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W105
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 55.5651	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 55.5651
Comments			

GM 453 Waste Characteristics			
A. Description of hazardous waste SPENT ACETONE			
B. EPA Hazardous Waste Code(s) D001, F003			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 9.2533	*UOM* KILOGRAMS	*Density* 0.78 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H061	*D. Total Quantity Shipped* 5.307
Site 2	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 3.9463
Comments			

GM 454 Waste Characteristics			
A. Description of hazardous waste STAINING OF POLYACRYLAMIDE GELS			
B. EPA Hazardous Waste Code(s) D001			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W219
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 1.5059	*UOM* KILOGRAMS	*Density* 1.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* COD980591184	*C. Management Method Code* H141	*D. Total Quantity Shipped* 1.5059
Comments			
1.E AQUEOUS GEL STAINING WASTE; METHANOL AND ACETIC ACID			

GM 455 Waste Characteristics			
A. Description of hazardous waste MIXTURE OF ETHYL ETHER AND HYDROCHLORIC ACID CONTAINING BARIUM, CHROMIUM, SILVER, CADMIUM, LEAD, & MERCURY COMPOUNDS.			
B. EPA Hazardous Waste Code(s) D001, D002, D005, D006, D007, D008, D009, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G22	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W203
F. Waste Minimization Code A	*G. Radioactive Mixed* Yes		
H. Quantity 4.3091	*UOM* KILOGRAMS	*Density* 0.9 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Site 1	*B. EPA ID of facility to which waste was shipped* FLD980711071	*C. Management Method Code* H061	*D. Total Quantity Shipped* 4.3091
Comments			

GM 456 Waste Characteristics			
A. Description of hazardous waste LEAD DECON DEBRIS			
B. EPA Hazardous Waste Code(s) D008, D011			
C. State Hazardous Waste Code(s)			
D. Source Code G19	*Management Method Code*	*Country* UNITED STATES	*E. Form Code* W002
F. Waste Minimization Code A	*G. Radioactive Mixed* No		
H. Quantity 25.4012	*UOM* KILOGRAMS	*Density* 0.0 sg	
On-site Generation and Management of Hazardous Waste			
Off-site Shipment of Hazardous Waste			
Comments			
1.D LEAD DECONTAMINATION			

Enclosure 2

Triad and N3B

Certifications

EPC-DO: 20-050

LA-UR-20-21356

Date: FEB 2 6 2020

CERTIFICATION

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

20 February 2020

Jennifer E. Payne
Division Leader
Environmental Protection and Compliance
Los Alamos National Laboratory

Date Signed

20 Feb 2020

Karen E. Armijo
Permitting and Compliance Program Manager
National Nuclear Security Administration
Los Alamos Field Office
U.S. Department of Energy

Date Signed

Document: 2019 Hazardous Waste Biennial Report
Date: February 2020

CERTIFICATION

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Elizabeth Lowes

2-21-2020

Elizabeth Lowes
Program Manager
Environment, Safety and Health
Newport News Nuclear BWXT
Los Alamos

Date Signed

For: Stephen F. Hall

2/24/2020

Arturo Q. Duran
Compliance and Permitting Manager
Environmental Management
Los Alamos Field Office

Date Signed

EPC-DO: 20-050
LA-UR-20-21356