



Environmental Programs
P.O. Box 1663, MS M991
Los Alamos, New Mexico 87545
(505) 606-2337/FAX (505) 665-1812



National Nuclear Security Administration
Los Alamos Site Office, MS A316
Environmental Restoration Program
Los Alamos, New Mexico 87544
(505) 667-4255/FAX (505) 606-2132

Date: June 30, 2008
Refer To: EP2008-0303

James P. Bearzi, Bureau Chief
Hazardous Waste Bureau
New Mexico Environment Department
2905 Rodeo Park Drive East, Building 1
Santa Fe, NM 87505-6303

Subject: Proof of Installation of Erosion Controls in Drainages to the 90s Line Pond

Dear Mr. Bearzi:

Enclosed please find two hard copies with electronic files of a series of photographs documenting installation of erosion control best management practices (BMPs) in drainages entering the 90s Line Pond [Consolidated Unit 16-008(a)-99]. These were required as part of the New Mexico Environment Department (NMED) "Notice of Approval with Direction Investigation Report for Consolidated Units 16-007(a)-99 and 16-008(a)-99 at Technical Area 16, Revision," dated February 11, 2008.

The BMPs were installed in the two major drainages to the 90s Line Pond on June 8, 2008. They consist of juniper bales designed to block sediment transport down the drainages into the pond. These bales will be maintained regularly along with other BMPs at Technical Area 16.

If you have any questions, please contact John McCann at (505) 665-1091 (jmccann@lanl.gov) or Woody Woodworth at (505) 665-5820 (lwoodworth@doel.gov).

Sincerely,

Susan G. Stiger, Associate Director
Environmental Programs
Los Alamos National Laboratory

Sincerely,

David R. Gregory, Project Director
Environmental Operations
Los Alamos Site Office

SS/DG/JM/DH:sm

Attachment: a/s

Cy: (w/enc.)

Don Hickmott, EP-CAP, MS M992
RPF, MS M707 (with two CDs)
Public Reading Room, MS M992

Cy: (Letter and CD only)

Laurie King, EPA Region 6, Dallas, TX
Steve Yanicak, NMED-OB, White Rock, NM
Woody Woodworth, DOE-LASO, MS A316
Peggy Reneau, WES-DO, MS M992
EP-CAP File, MS M992

Cy: (w/o enc.)

Tom Skibitski, NMED-OB, Santa Fe, NM
Alison Bennett, DOE-LASO (date-stamped letter emailed)
Susan G. Stiger, ADEP, MS M991
Alison M. Dorries, WES-DO, MS M992
Dave McInroy, EP-CAP, MS M992
IRM-RMMSO, MS A150



Figure 1 Drainages into the 90s Line Pond before best management practice (BMP) installation



Figure 2 Drainages into the 90s Line Pond after BMP installation