



Environmental Programs P.O. Box 1663, MS M991 Los Alamos, New Mexico 87545 (505) 606-2337/FAX (505) 665-1812



National Nuclear Security Administration Los Alamos Site Office, MS A316 Environmental Restoration Program Los Alamos, New Mexico 87544 (505) 667-4255/FAX (505) 606-2132

Date: DEC 0 6 2010 Refer To: EP2010-0533

James Bearzi, Bureau Chief Hazardous Waste Bureau New Mexico Environment Department 2905 Rodeo Park Drive East, Building 1 Santa Fe, NM 87505-6303

Subject: Erosion Controls Associated with Fishladder Canyon [Solid Waste Management Unit 16-003(o)]

Dear Mr. Bearzi:

This letter documents stormwater management following mitigation activities on Solid Waste Management Unit (SWMU) 16-003(o)—"Fishladder Canyon." This letter is required as part of the New Mexico Environment Department's (NMED's) approval with modifications for the Phase II investigation report for the TA-16-340 Complex, Revision 1, dated February 9, 2009.

Stormwater controls were installed on the mesa top and north-facing hillslope draining into Fishladder Canyon and in the main Fishladder Canyon drainage. Controls included straw wattles on the mesa top and hillslope (see attached Figures 1 to 3) that were designed to control surface erosion and sediment transport by establishing a permanent vegetation cover. Previously existing controls in the main channel include a rock check dam and a gabion structure, which were designed to reduce flow velocities and sediment.

SWMU 16-003(o) is included in Los Alamos National Laboratory's National Pollutant Discharge Elimination System Stormwater Individual Permit (Permit No. NM0030759). Stormwater controls at the SWMU are inspected under the Individual Permit Program at least once per year or following a 0.25 in./30 min or greater intensity rain event or following an exceedance of permit-specified stormwater standards. Controls at this SWMU were inspected six times this year between June 11 and October 21, following six separate rain events. Maintenance issues were identified for storms on July 8, 2010, and July 29, 2010, and promptly resolved. Photos of individual controls are not required as part of the Individual Permit Program inspection procedure and are not available for this report.

James Bearzi

If you have any questions, please contact John McCann at (505) 665-1091 (jmccann@lanl.gov) or Woody Woodworth at (505) 665-5820 (lwoodworth@doeal.gov).

Sincerely,

Michael J. Graham/Associate Director Environmental Programs Los Alamos National Laboratory Sincerely,

5 Blue

George J. Rael, Manager Environmental Projects Office Los Alamos Site Office

MG/GR/DM/JM:sm

Enclosures: Two hard copies with electronic files - Figures (LA-UR-10-7864)

- Cy: (w/enc.) Neil Weber, San Ildefonso Pueblo Woody Woodworth, DOE-LASO, MS A316 John McCann, EP-CAP, MS M992 RPF, MS M707 (w/ two CDs) Public Reading Room, MS M992
- Cy: (Letter and CD and/or DVD only) Laurie King, EPA Region 6, Dallas, TX Steve Yanicak, NMED-DOE-OB, MS M894 William Alexander, EP-BPS, MS M992

Cy: (w/o enc.) Tom Skibitski, NMED-OB, Santa Fe, NM Annette Russell, DOE-LASO (date-stamped letter emailed) Dave McInroy, EP-CAP, MS M992 (date-stamped letter emailed) Michael J. Graham, ADEP, MS M991 (date-stamped letter emailed)