



Environmental Programs
P.O. Box 1663, MS M991
Los Alamos, New Mexico 87545
(505) 606-2337/FAX (505) 665-1812



National Nuclear Security Administration
Los Alamos Site Office, MS A316
Environmental Restoration Program
Los Alamos, New Mexico 87544
(505) 667-4255/FAX (505) 606-2132

Date: **JAN 14 2011**
Refer To: EP2011-0007

James Bearzi, Bureau Chief
Hazardous Waste Bureau
New Mexico Environment Department
2905 Rodeo Park Drive East, Building 1
Santa Fe, NM 87505-6303

Subject: Submittal of the Work Plan to Plug and Abandon Test Well 3

Dear Mr. Bearzi:

Enclosed please find two hard copies with electronic files of the Work Plan to Plug and Abandon Test Well 3. This plan fulfills the requirement in the New Mexico Environment Department's approval with modifications for the Technical Area 21 monitoring well network evaluation and recommendations letter, dated December 2, 2010.

If you have any questions, please contact Bruce Wedgeworth at (505) 231-0108 (brucew@lanl.gov) or Hai Shen at (505) 665-5046 (hshen@doeal.gov).

Sincerely,

Michael J. Graham, Associate Director
Environmental Programs
Los Alamos National Laboratory

Sincerely,

George J. Rael, Manager
Environmental Projects Office
Los Alamos Site Office

MG/GR/PH/BC/ME:sm

Enclosures: Two hard copies with electronic files – Work Plan to Plug and Abandon Test Well 3
(LA-UR-11-0185)

Cy: (w/enc.)

Neil Weber, San Ildefonso Pueblo
Hai Shen, DOE-LASO, MS A316
Bruce Wedgeworth, EP-TA-21, MS C349
RPF, MS M707 (w/ two CDs)
Public Reading Room, MS M992

Cy: (Letter and CD and/or DVD only)

Laurie King, EPA Region 6, Dallas, TX
Steve Yanicak, NMED-DOE-OB, MS M894
Mark Everett, EP-ET (w/ MS Word files on CD)
William Alexander, EP-BPS, MS M992

Cy: (w/o enc.)

Tom Skibitski, NMED-OB, Santa Fe, NM
Annette Russell, DOE-LASO (date-stamped letter emailed)
Paul Huber, EP-TA-21, MS C349 (date-stamped letter emailed)
Michael J. Graham, ADEP, MS M991 (date-stamped letter emailed)