

FIGURES



Figure 1 Seed, mulch, and straw wattles on bare slope draining to 90s Line Pond, November 2011



Figure 2 Juniper bale check dam in channel draining to 90s Line Pond



Figure 3 Juniper bale check dam in channel draining to 90s Line Pond repaired in November 2011



Figure 4 Juniper bale check dam in channel draining to 90s Line Pond repaired in November 2011



Figure 5 Juniper bale check dam in channel draining to 90s Line Pond repaired in November 2011