FIGURES



Figure 1 Juniper bale check dam in channel draining to 90s Line Pond, November 2013



Figure 2 Juniper bale check dam in channel draining to 90s Line Pond, November 2013

EP2013-0290 LA-UR-13-28929



Figure 3 Juniper bale check dam in channel draining to 90s Line Pond, November 2013



Figure 4 Slope draining to 90s Line Pond stabilized with mulch and natural pine needle cover, November 2013