



Environmental Programs
 P.O. Box 1663, MS M991
 Los Alamos, New Mexico 87545
 (505) 606-2337/FAX (505) 665-1812



National Nuclear Security Administration
 Los Alamos Site Office, MS A316
 Environmental Restoration Program
 Los Alamos, New Mexico 87544
 (505) 667-4255/FAX (505) 606-2132

Date: MAR 25 2010
 Refer To: EP2010-0119

James Bearzi, Bureau Chief
 Hazardous Waste Bureau
 New Mexico Environment Department
 2905 Rodeo Park Drive East, Building 1
 Santa Fe, NM 87505-6303

Subject: Submittal of the Work Plan to Plug and Abandon Test Well TW-4

Dear Mr. Bearzi:

Enclosed please find two hard copies with electronic files of the work plan to Plug and Abandon Test Well TW-4.

If you have any questions, please contact Ted Ball at (505) 665-3996 (tedball@lanl.gov) or Tom Whitacre at (505) 665-5042 (twhitacre@doeal.gov).

Sincerely,

Sincerely,

Bruce Schappell, Executive Director
 Environmental Programs – Recovery Act Projects
 Los Alamos National Laboratory

Everett Trollinger, Federal Project Director
 Environmental Projects – ARRA
 Los Alamos Site Office

BS/ET/TB/ME:sm

Enclosures: Two hard copies with electronic files – Work Plan to Plug and Abandon Test Well
TW-4 (LA-UR-10-1423)

Cy: (w/enc.)
Neil Weber, San Ildefonso Pueblo
Hai Shen, DOE-LASO, MS A316
Mark Everett, EP-ET-DO, MS M992
RPF, MS M707 (with two CDs)
Public Reading Room, MS M992

Cy: (Letter and CD only)
Laurie King, EPA Region 6, Dallas, TX
Steve Yanicak, NMED-DOE-OB, MS M894
Kristine Smeltz, EP-WES, MS M992

Cy: (w/o enc.)
Tom Skibitski, NMED-OB, Santa Fe, NM
Annette Russell, DOE-LASO (date-stamped letter emailed)
Ted Ball, EP-ARRA Project, MS MS C348
Michael J. Graham, ADEP, MS M991
IRM-RMMSO, MS A150 (date-stamped letter emailed)