

SUSANA MARTINEZ Governor

JOHN A. SANCHEZ Lieutenant Governor

NEW MEXICO ENVIRONMENT DEPARTMENT

Hazardous Waste Bureau

2905 Rodeo Park Drive East, Building 1 Santa Fe, New Mexico 87505-6303 Phone (505) 476-6000 Fax (505) 476-6030 www.nmenv.state.nm.us



RYAN FLYNN Cabinet Secretary-Designate

> BUTCH TONGATE Deputy Secretary

TOM BLAINE, P.E. Director Environmental Health Division

EP2013-5143

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

July 16, 2013

11 . 1944

Peter Maggiore Assistant Manager U.S. Department of Energy National Nuclear Security Administration Los Alamos Site Office 3747 West Jemez Rd, MS A316 Los Alamos, NM 87544 Jeffrey D. Mousseau Associate Director Environmental Programs Los Alamos National Security, L.L.C. P.O. Box 1663, MS M991 Los Alamos, NM 87545

RE: EXTENSION REQUEST TO SUBMIT THE DRILLING WORK PLANS FOR R-54 AND R-55i REPLACEMENT WELLS LOS ALAMOS NATIONAL LABORATORY EPA ID#NM0890018 HWB-LANL-08-001

Dear Messrs. Maggiore and Mousseau:

The New Mexico Environment Department (NMED) is in receipt of the United States Department of Energy (DOE) and Los Alamos National Security, L.L.C.'s (collectively, the Permittees) document entitled *Request for Extension to Submit the Drilling Work Plans for R-54 and R-55i Replacement Wells* (Work Plans) dated June 27, 2013 and referenced by EP2013-0131.

The Permittees submitted a report summarizing the results of attempted rehabilitation and testing of well R-54 (*Evaluation to Determine the Cause of Reducing Conditions* Observed in Regional Aquifer Monitoring Wells R-54 and R-61 (Evaluation) dated April 11, 2013 and referenced by EP2013-0068) that provided evidence that the well was not capable of producing representative data due to the introduction of hammer oil during drilling. Based on the information provided in the Evaluation, NMED subsequently

Messrs. Maggiore and Mousseau July 16, 2013 Page 2

directed the Permittees, in a letter dated May 28, 2013, to submit the subject Work Plans to replace wells R-54 and R-55i. Well R-55i also displays characteristics indicating the presence of hammer oil.

The date for submittal of the Work Plans for the replacement of wells R-54 and R-55i has been changed from July 15, 2013 to **December 15, 2013**, as requested.

NMED is concerned over delays that affect the progress of groundwater characterization and monitoring; however, NMED is aware of the current uncertainties associated with the allocation of DOE resources to LANS to fund groundwater monitoring and cleanup at the Laboratory. Based on the chemical analytical data acquired to date, the water chemistry has been altered in wells R-54 and R-55i. Recent rehabilitation efforts conducted at similarly affected well R-61 were not successful; therefore, it does not appear likely that the wells will be adequate to serve as part of the Technical Area 54 monitoring well network. Regardless, the request has been automatically granted because NMED did not respond in writing within ten business days as specified in Consent Order Section III.J.2.

Please contact Dave Cobrain at (505) 476-6055 if you have questions.

Sincerely, John E. Kieling

Chief Hazardous Waste Bureau

cc: T. Blaine, NMED EHD
D. Cobrain, NMED HWB
N. Dhawan, NMED HWB
B. Wear, NMED HWB
M. Dale, NMED HWB
J. Kulis, NMED HWB
J. Kulis, NMED HWB
S. Yanicak, NMED DOE OB, MS M894
L. King, EPA 6PD-N
S. Paris, EP-CAP, MS A992
C. Rodriguez, DOE-LASO, MS A316
H. Shen, DOE-LASO, MS A316

File: Reading and LANL 2013 -GroundwaterTA-54, R-54 and R-55i

New Mexico Environment Department Hazardous Waste Bureau 2905 Rodeo Park Drive East, Bldg.1 Santa Fe, New Mexico 87505





016H26523547

\$06.110 07/17/2013 Mailed From 87505 US POSTAGE

Hasler

Jeffrey D. Mousseau, Associate Director Environmental Programs Los Alamos National Security, LLC P.O. Box 1663, MS K<u>A91</u> Los Alamos, New Mexico 87545

իսուվվիկվիրդեմիսինկուղիկույրն

01-13-13P

NAM Z# DATE