

---

**Subject:** Remediated Nitrate Salts-Bearing Waste Container Isolation Plan - Missed Inspection

---

**From:** Haagenstad, Mark P

**Sent:** Tuesday, May 02, 2017 5:10 PM

**To:** Kieling, John, NMENV <john.kieling@state.nm.us>; Dhawan, Neelam, NMENV <neelam.dhawan@state.nm.us>; Briley, Siona, NMENV <Siona.Briley@state.nm.us>

**Cc:** Bretzke, John Clifford <jbretzke@lanl.gov>; Grieggs, Tony <grieggst@lanl.gov>; Vigil-Holterman, Luciana R <luciana@lanl.gov>; Diaz, Tammy <tdiaz@lanl.gov>; Armijo, Karen <Karen.Armijo@nnsa.doe.gov>; Rhodes, David <David.Rhodes@em.doe.gov>; Duran, Arturo Q. <Arturo.Duran@em.doe.gov>

**Subject:** Remediated Nitrate Salts-Bearing Waste Container Isolation Plan - Missed Inspection

Dear Mr. Kieling:

Per a conversation earlier today (5/2/2017) with Neelam Dhawan or your staff, The Department of Energy (DOE) and Los Alamos National Security, LLC (collectively the Permittees) are providing notification of the following missed inspections that is required by the LANL Nitrate Salt-Bearing Waste Container Isolation Plan, Revision 8 (Isolation Plan):

On Saturday April 29, 2017, inspections of the remediated nitrate salt-bearing waste containers (RNS) were not performed. Due to inclement weather conditions, daily temperature monitoring and visual inspections were not conducted. In addition, headspace gas sampling and analysis was not performed on containers 68685 and 69490.

All required inspections resumed on Sunday April 30, 2017. Required inspection measurements were all within normal parameters. The Permittees will provide a summary of this information in the May 2017 Monthly Technical Summary Report.

Please contact me if additional information would be helpful.

Mark Haagenstad

EPC-CP

Office: (505) 665-2014

Mobile: (505) 699-1733