



Plate 1 VOCs detected in vapor samples at MDA L

- Disposal shaft
- Disposal pit or impoundment
- Vapor-monitoring well
- Existing structure
- Potentially removed structure
- MDA
- MDA L
- TA-54
- Security fence
- Security gate
- Paved road
- Paved parking
- Unpaved road
- 100-ft contour
- 10-ft contour

GIS: Dave Frank  
Date: 07-July-2011  
Map Number: 11-002-03  
New Mexico State Plane Coordinate System  
Central Zone (3022)  
North American Datum (NAD 83)  
National Geospatial Vertical Datum  
1988 (100 ft contours)

US Survey Feet  
Disclaimer: This map was created for work processes associated with the MDA L Periodic Monitoring Report. All other uses should be confirmed with LANL EP-ETIC staff.  
All organic constituents are in µg/m³

