
**Certification of Installation of
Enhanced Control Measures
at CDV-SMA-2.41**

LA-UR-14-23980

[This page intentionally blank.]

**LOS ALAMOS NATIONAL LABORATORY
CERTIFICATION OF ENHANCED CONTROL MEASURES**

PF: V008


CDV-SMA-2.41

Sites: 16-018

The following certification was performed in accordance with NPDES Permit No. NM0030759, Part I.E.1 (c), which requires the Permittees (i.e. DOE and LANS) to certify the completion of the installation of control measures within 30 days of completion of the installation of all such measures at the site.

CERTIFICATION STATEMENT OF AUTHORIZATION

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware there are significant penalties for submitting false information including the possibility of fine and imprisonment for knowing violations."



Environmental Programs
Corrective Actions Program
Los Alamos National Laboratory

June 25, 2014
Date



Los Alamos Field Office
National Nuclear Security Administration

6-26-2014
Date

[This page intentionally blank.]

**LOS ALAMOS NATIONAL LABORATORY
CERTIFICATION OF ENHANCED CONTROL MEASURES**

PF: V008

CDV-SMA-2.41

Sites: 16-018

In accordance with Part I.E.1 (a), the design, installation, and documentation of enhanced control measures reasonably expected to achieve compliance with target action levels identified in the Permit for all Sites within the identified SMA drainage area have been completed.

Enhanced Control Measure Description:			
BMP ID	Type of Control Measure	Control Measure	Photo ID
V00803010013	Berms	Earthen Berm	38572-4.JPG
V00804010014	Channel/Swale	Earthen Channel/Swale	38572-1.JPG
V00806010012	Check Dam	Rock Check Dam	38572-3.JPG

NPDES PERMIT NO. NM0030759

LA-UR-14-23980

LOS ALAMOS NATIONAL LABORATORY
CERTIFICATION OF ENHANCED CONTROL MEASURES

PF: V008

CDV-SMA-2.41

Sites: 16-018

Photos:



Photo: 38572-1.JPG

V00804010014

Channel/Swale

- Earthen Channel/Swale

NPDES PERMIT NO. NM0030759

LA-UR-14-23980

LOS ALAMOS NATIONAL LABORATORY
CERTIFICATION OF ENHANCED CONTROL MEASURES

PF: V008

CDV-SMA-2.41

Sites: 16-018



Photo: 38572-3.JPG

V00806010012

Check Dam

- Rock Check Dam

LOS ALAMOS NATIONAL LABORATORY
CERTIFICATION OF ENHANCED CONTROL MEASURES

PF: V008

CDV-SMA-2.41

Sites: 16-018



Photo: 38572-4.JPG

V00803010013

Berms

- Earthen Berm

LOS ALAMOS NATIONAL LABORATORY
CERTIFICATION OF ENHANCED CONTROL MEASURES

PF: V008

CDV-SMA-2.41

Sites: 16-018

