

FIGURES



Figure 1 Downslope from mesa top into Fishladder Canyon



Figure 2 Upslope from bottom of Fishladder Canyon



Figure 3 East down Fishladder Canyon access road



Figure 4 Damaged rock check dam



Figure 5 Repaired rock check dam