LA-UR-12-25356

Approved for public release; distribution is unlimited.

Title:	Status Report, Ancho/Chaquehui Watershed July 1–November 30, 2012
Author(s):	Steve Veenis
Intended for:	Public
Purpose:	This <i>Status Report</i> has been prepared to facilitate public review of activities under the Individual Storm Water Permit (National Pollutant Discharge Elimination System Permit No. NM0030759) (IP). This report, not required by the IP, updates the 2011 Annual Report (published on March 1, 2012). Further, it summarizes precipitation, monitoring, inspection and maintenance, corrective action, and compliance status at specific solid waste management units and areas of concern listed in the IP. The report will be available on Los Alamos National Laboratory's public website established as required under Part 1.I (7) of the IP.



Los Alamos National Laboratory, an affirmative action/equal opportunity employer, is operated by the Los Alamos National Security, LLC for the National Nuclear Security Administration of the U.S. Department of Energy under contract DE-AC52-06NA25396. By acceptance of this article, the publisher recognizes that the U.S. Government retains a nonexclusive, royalty-free license to publish or reproduce the published form of this contribution, or to allow others to do so, for U.S. Government purposes. Los Alamos National Laboratory requests that the publisher identify this article as work performed under the auspices of the U.S. Department of Energy. Los Alamos National Laboratory does not endorse the viewpoint of a publich; as an institution, however, the Laboratory does not endorse the viewpoint of a publication or guarantee its technical correctness.

LA-UR-12-25356 February 2013 EP2012-0241

STATUS REPORT

Ancho/Chaquehui Watershed July 1–November 30, 2012

INDIVIDUAL STORM WATER NPDES PERMIT No. NM0030759



OVERVIEW

Los Alamos National Security, LLC, under the direction of the National Nuclear Security Administration, has prepared this *Status Report* to facilitate public review of activities under the Individual Storm Water Permit (National Pollutant Discharge Elimination System Permit No. NM0030759) (IP). This report, not required by the IP, updates the 2011 Annual Report published on March 1, 2012. Further, for the July 1–November 30, 2012, time period, it summarizes precipitation, monitoring, inspection and maintenance, corrective action, and compliance status at specific solid waste management units and areas of concern, commonly referred to as "Sites." A previous report was prepared summarizing these activities from January 1–June 30, 2012. Both reports will be available on Los Alamos National Laboratory's public website as required under Part 1.I (7) of the IP. This website may be found at http://www.lanl.gov/community-environment/environmental-stewardship/protection/compliance/individual-permit-stormwater/index.php.

Within the Ancho/Chaquehui watershed, 39 Sites are monitored at 21 site monitoring areas (SMAs). Highlights of work performed from July 1–November 30, 2012, include the following items.

- Baseline controls were replaced at 1 SMA, and enhanced controls were certified as corrective action measures at 2 SMAs.
- Nineteen samplers were activated. Two confirmatory samples were collected as a result of 9 measureable storm events. Sixty-three storm event inspections were required.
- As of November 30, 2012, baseline monitoring is continuing at 17 SMAs, corrective action was initiated at 4 SMAs, and 1 Site was issued a Certificate of Completion under the Compliance Order on Consent (the Consent Order).
- There were no incidents of noncompliance that could potentially endanger health or the environment during this time period, July 1–November 30, 2012.

PRECIPITATION

Within the watershed, 3 precipitation gages monitor and report precipitation activity during the field season. These gages and their activity levels from July 1–November 30, 2012, are shown in Table 1. There were 9 measurable storm events (an event with precipitation intensity of 0.25 in. within 30 min).

Adverse Weather

No adverse weather events affected IP activities.

MONITORING

Samplers Activated

Table 1Precipitation Activity forJuly 1–November 30, 2012

Rain Gage	Related SMAs	Measurable Storm Events	Storm Event Inspections Conducted
RG265	4	07/04/12 08/02/12 08/26/12	4 4 4
RG267.4	2	07/07/12 08/26/12 09/10/12	2 2 2
RG340	15	07/04/12 08/16/12 09/10/12	15 15 15

Nineteen samplers were activated on July 1, 2012, and an additional 2 samplers were activated after July 1 and prior to November 30. Two samplers were deactivated following the collection of an extended baseline sample, and 6 samplers were shut down for the winter, leaving 13 samplers activated on November 30, 2012. The remaining samplers were shut down for the winter in early December 2012.

Samples Collected

A single extended baseline monitoring sample was collected from CHQ-SMA-1.03 and from CHQ-SMA-2 on July 4, 2012.

Sampler Placement

Samplers associated with monitoring locations for Sites were placed in accordance with coordinate locations provided in the Site Discharge Pollution Prevention Plan, Revision 1, Volume 5 (SDPPP, R1, V5).

INSPECTION AND MAINTENANCE

Post-Storm Inspections

Sixty-three post-storm inspections were required for the Sites as a result of 9 measureable storm events.

Visual Inspections

Two visual inspections were conducted where a target action level (TAL) was exceeded.

Significant Event Inspections

No significant events that could impact the control measures and environmental conditions occurred that required a Site to be reevaluated and inspected under Part 1.G (1) of the IP.

Annual Erosion Inspections

No annual erosion reevaluation inspections were conducted during the July 1–November 30, 2012, time period. All annual inspections for the 21 SMAs in the watershed were completed prior to July 1, 2012.

Control Maintenance

Eight control maintenance activities were conducted.

CORRECTIVE ACTION

Augmented Control Installations

No additional controls were installed during the July 1–November 30, 2012, time period. The additional controls are generally installed at to "augment" baseline controls. These Sites are not in corrective action because monitoring has not shown a TAL exceedance.

Baseline Control Replacements

Baseline control replacements were completed at 1 SMA and are presented in Appendix A. The purpose of a control replacement is to maintain or upgrade the existing certified baseline controls at an SMA.

Enhanced Control Installations

When a sample that exceeds TALs is collected from an SMA, these Sites advance to corrective action. One of the corrective action options is to construct enhanced controls.

When all the enhanced controls are installed, a certification of the installed controls is submitted to the U.S. Environmental Protection Agency (EPA) and New Mexico Environment Department (NMED) and is made available on the IP website. Enhanced controls were certified at 2 SMAs:

- A-SMA-2.7 on August 23, 2012
- CHQ-SMA-1.02 on October 24, 2012

COMPLIANCE STATUS

Baseline Confirmation Is Complete

All confirmation monitoring to assess baseline controls were above TALs; therefore, corrective action is required at the Sites.

Baseline Monitoring Is Extended

As of November 30, 2012, baseline monitoring is continuing at 17 SMAs. A confirmation monitoring sample has not been collected at these SMAs. Baseline monitoring will be extended under the IP until analytical results are received from the first confirmation sample collected.

Compliance Status Categories

Compliance status is tracked for each Site throughout the year. The categories used for tracking include the following:

- Baseline Confirmation Complete—All confirmation monitoring results for all pollutants of concern at the SMA are at or below TALs, and corrective action is not required at the Sites. No further sampling is required.
- Baseline Monitoring Extended—Baseline confirmation monitoring is in progress, and no storm water from a measurable storm event has been collected. There has been no TAL exceedance.
- Corrective Action Initiated—A sample was collected during baseline confirmation monitoring, and analytical results show at least one pollutant concentration is above TAL, resulting in initiation of corrective action. Corrective action may include
 - installing enhanced control measures,
 - installing control measures that totally retain storm water,
 - installing control measures that totally eliminate the exposure of pollutants, or
 - receiving a Certificate of Completion from NMED.
- Enhanced Control Corrective Action Monitoring— Confirmation monitoring at an SMA is initiated to determine how well enhanced controls are performing. This monitoring occurs after certification that the enhanced control measures have been installed and are complete.
- Corrective Action Complete—Completion of corrective action is demonstrated by one of the following:
 - Analytical results from enhanced control monitoring show pollutant concentrations for all pollutants of concern at the Site to be at or below applicable TALs; or
 - Control measures that totally retain and prevent the discharge of storm water have been installed at the Site; or
 - Control measures that totally eliminate exposure of pollutants to storm water have been installed at the Site; or
 - The Site has achieved Resource Conservation and Recovery Act "no further action" status or a Certificate of Completion from NMED.

Corrective Action Is Initiated

As of November 30, 2012, corrective action has been initiated at 4 SMAs (12 Sites). See Appendix B for a list of these SMAs and associated Sites.

Enhanced Control Corrective Actions Are Monitored

As of November 30, 2012, enhanced control corrective action monitoring has started at 2 SMAs.

Corrective Action Complete

One Certificate of Completion under the Consent Order was issued on November 29, 2012, for Site 39-002(c), 1 of 2 Sites monitored under A-SMA-2.7.

DOCUMENTS SUBMITTED

From July 1–November 30, 2012, no new IP Program documents were submitted to EPA Region 6.

IP documents for the IP Program can be found on the IP website at <u>http://www.lanl.gov/community-</u> environment/environmental-stewardship/protection/compliance/individual-permit-stormwater/index.php.

Site Monitoring Area	Control Description	Install Date	Control Category
CHQ-SMA-6	Q009-03-06-0033 Berm–Straw Wattles	10/01/2012	Replaced baseline control
	Q009-03-06-0034 Berm–Straw Wattles	10/01/2012	Replaced baseline control
	Q009-03-06-0035 Berm–Straw Wattles	10/01/2012	Replaced baseline control

APPENDIX A Additional Controls Installed or Replaced and Baseline Controls Replaced between July 1–November 30, 2012

APPENDIX B Sites and Site Monitoring Areas in Corrective Action Initiated Status as of November 30, 2012, within the Ancho/Chaquehui Watershed

Site Monitoring Area	Site	
A-SMA-2.7	39-002(c) 39-008	
CHQ-SMA-1.02	33-004(h) 33-008(c) 33-011(d) 33-015	
CHQ-SMA-1.03	33-017 C-33-001 C-33-003 33-012(a) 33-008(c)	
CHQ-SMA-2	33-004(d) 33-007(c) C-33-003	