

Sampling Locations:

⊗ Borehole

Elevation:

20 ft contour

Structures:

10-66 Former LANL TA-10

Roads:

Former LANL TA-10 (dirt)

Sample Text:

Location ID (*2007* - red or underlined, *historical* - black or not underlined)

Sample description (sample ID, depth (ft), media)

10-01017
RE10-07-5304 0.00-0.50 SOIL
Copper 5.5
Selenium 0.5 (J)

Analyte data (analyte, result, optional qualifier code)

Result Qualifiers:
J = Estimated value
J+= Estimated value biased high
J- = Estimated value biased low

Note: All analytical results reported in milligrams per kilogram (mg/kg) except as noted.

A label containing only a location ID indicates that no analytes were detected at concentrations above background values or detection limits.

QBOF is equivalent to QBO



This map was created for work processes associated with the Environment and Remediation Support Services. All other uses for this map should be confirmed with LANL EP-ERSS staff.

Plate 9, SWMU 10-004(a) organic chemical concentrations detected

Map created by R. Leishman, 10 January 2008, Map #08-03 BayoCanyonAgg